## ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager

Freightliner Dealers – U.S. and Canada Western Star and Sterling Dealers – U.S. and Canada FCCC Dealers – U.S. and Canada Direct Warranty Customers – U.S. and Canada Export Distributors

## Daimler Trucks North America LLC

## WARRANTY CAMPAIGNS DEPARTMENT

P.O. Box 4090 800-547-0712 Portland, Oregon 97208-4090

> If you have questions about this Letter, please submit your inquiry on the Web using the WSC Link on DTNAConnect

REF #: ICI19-013

Effective: 03/20/19
Release: 03/20/19

SUBJECT: INT FL806 - Revised Bulletin

This letter is to inform you that a revised bulletin for Interim Recall INT FL806 Freightliner Cascadia Steering Wheel Airbags is available on DTNAConnect. Please print and use the revised bulletin for all work under INT FL806 from this point forward.

REVISION: The incorrect clockspring replacement part was listed in the parts table. The correct clockspring part number is **14-19090-000 (CLOCKSPRING-STEERING WHEEL)**. The parts table has been corrected.

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through the WSC Link on DTNAConnect.