



## **Chronology of Defect / Noncompliance Determination**

**Provide the chronology of events leading up to the defect decision or test data for the noncompliance decision.:**

*Late October 2018, DTNA engineering testing process identified incorrect software handling of ABS malfunction indicator lamp. October 2018 – January 2019, DTNA evaluates the software with further testing to determine the scope of the issue. Late January 2019, DTNA determined the potential issue affects customer demonstration vehicles outside of our test fleet and began an extensive investigation to identify that population for repair considerations. February 2019, with an abundance of caution, DTNA decided to initiate a voluntary recall.*

## **Identify the Remedy**

**Describe the defect/noncompliance remedy program, including the manufacture's plan for reimbursement.**

*The ABS module will be reprogrammed so the ABS fault code will remain after a key cycle and illuminate the ABS lamp. Repairs will be performed by Daimler Trucks North America authorized service facilities. Copies of the reimbursement plan will be submitted as a supplemental report when available.*

## **Identify the Recall Schedule**

**Describe the recall schedule for notifications.:**

*Customer notification will be made by first class mail using Daimler Trucks North America records to determine the customers affected.*

**Planned Dealer Notification Begin Date:** 04/27/2019

**Planned Dealer Notification End Date:** 04/27/2019

**Planned Owner Notification Begin Date:** 04/27/2019

**Planned Owner Notification End Date:** 04/27/2019

**Manufacture's identification code for this recall (if applicable):** FL-810

**DTNA Representative**



Andy Jones

Manager

Compliance and Regulatory Affairs