OMB Control No.: 2127-0004

Part 573 Safety Recall Report

19V-171

Manufacturer Name: Daimler Trucks North America LLC

Submission Date: MAR 05, 2019 NHTSA Recall No.: 19V-171 Manufacturer Recall No.: FL-812



Manufacturer Information:

Manufacturer Name: Daimler Trucks North America LLC

Address: 4747 N. Channel Avenue

Portland OR 97217-3849

Company phone: 800-745-8000

Population:

Number of potentially involved : 81 Estimated percentage with defect : 100%

Vehicle Information:

Vehicle 1: 2019-2019 Western Star 4700

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : Power Train : NR

Descriptive Information: Certain trucks built within the production dates equipped with certain speedometers.

Production Dates: NOV 07, 2018 - NOV 26, 2018

Vehicle 2: 2019-2019 Western Star 4900

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : Power Train : NR

Descriptive Information: Certain trucks built within the production dates equipped with certain speedometers.

Production Dates: NOV 07, 2018 - NOV 26, 2018

Description of Noncompliance:

Description of the Distance traveled is accumulated in kilometers by the odometer but the label

Noncompliance: on the dial face says miles. FMVSS 101 Table 2 requires if distance is

accumulated in kilometers the display needs to be labeled in kilometers.

FMVSS 1: 101 - Control and displays

FMVSS 2: NR

Description of the Safety Risk: The display of the vehicle's accumulated distance in kilometers while the

gauge is labeled miles, could lead to driver confusion, and inspections and maintenance may occur sooner than needed, as well as possible incorrect

assumptions about driver speed.

Description of the Cause: NR Identification of Any Warning NR that can Occur:

Supplier Identification:

Component Manufacturer

Name: Pacific Insight

Address: NR

NR

Country: NR

Chronology:

In November 2018, DTNA received a customer complaint regarding an odometer alleged to be displaying distance in Kilometers, while it was labeled miles. November, 2018 through January 2019, DTNA investigated the issue to identify scope, root cause and population. DTNA also reached out to external counsel as part of the investigation. February 2019, DTNA received clarification from outside counsel that the issue may be noncompliant with FMVSS 101. February 28, 2019, DTNA decided to voluntarily recall the affected vehicles.

Description of Remedy:

Description of Remedy Program: Speedometers will be replaced by Daimler Trucks North America

authorized service facilities. Copies of

the reimbursement plan will be submitted as a supplemental report when

available.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: Customer notification will be made by first class mail using Daimler

Trucks North America records to

determine the customers affected.

Planned Dealer Notification Date: MAY 03, 2019 - MAY 03, 2019

Planned Owner Notification Date: MAY 03, 2019 - MAY 03, 2019

Part 573 Safety Recall Report	19V-171	Page 3
* NR - Not Reported		
The information contained in this report was submitted	d pursuant to 49 CFR §573	