

March 9, 2019

Version 1

## Safety Recall: Driver's Airbag Replacement Inflator Can Be Over-Pressurized (Module Replacement)

### AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2004-06	TL	ALL	Check the iN VIN status for eligibility.

### BACKGROUND

In certain vehicles, the **replacement** driver's (front) airbag inflator (from either a previous recall repair or an airbag module replacement) could produce excessive internal pressure during airbag deployment. If an affected airbag deploys, the increased internal pressure may cause the inflator casing to rupture. Metal fragments could pass through the airbag cushion material, possibly causing injury or fatality to vehicle occupants.

When this temporary placeholder bulletin appears during an iN VIN Status Inquiry, this vehicle is subject to a Safety Recall. This vehicle is on **STOP SALE** until further notice. Check for an iN message for further details. Refrain from calling Tech Line for updates.

**This bulletin will be updated once Parts Information, Warranty Claim Information, Inspection Procedures, and Repair Procedures are available.**

END

**CLIENT INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.