

Part 573 Safety Recall Report

19V-186

Manufacturer Name : M H EBY**Submission Date :** MAR 07, 2019**NHTSA Recall No. :** 19V-186**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : M H EBY

Address : 1194 Main St
Blue Ball PA 17506

Company phone : 354-4971

Population :

Number of potentially involved : NR

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2019-2020 EBY Gooseneck Livestock

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : We were notified by Dexter Axle Company of a population of 8000 and 10000 pound axles which may not have had the inner wheel bearings greased per Dexter's specification. This notification included grease pack axles and does not include oil bath axles. We purchased 219 of the potential axles

Production Dates : DEC 03, 2018 - MAR 01, 2019

VIN Range 1 : Begin : NR End : NR

 Not sequential**Description of Defect :**

Description of the Defect : I8000 and 10000 pound axles which may not have had the inner wheel bearings greased per Dexter's specification.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The wheel hub may overheat and smoke, increasing the risk of a fire or the bearing may fail, affecting handling and increasing the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Dexter Axle Company
Address : 2900 Industrial Parkway East
Elkhart INDIANA 46516
Country : United States

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR
How Remedy Component Differs from Recalled Component : NR
Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : NR - NR
Planned Owner Notification Date : NR - NR

* NR - Not Reported