NR

Part 573 Safety Recall Report

Manufacturer Name :	Thor Motor Coach
Submission Date :	MAR 27, 2019
NHTSA Recall No. :	19V-240
Manufacturer Recall No. :	RC000168

Manufacturer Information :

Manufacturer Name : Thor Motor Coach Address : PO Box 1486 701 County Road 15 Elkhart IN 46515 Company phone : 877-500-1020

Vehicle Information :

Vehicle 1:	2018-2019 C	hateau ALL			
Vehicle Type :			VEHICLES		
Body Style :			121110220		
Power Train :					
Descriptive Information :	 It has been discovered that on Certain MY 2018/2019 Chateau, Four Winds, Magnitude, Omni Motorhomes, the Voyager Mirror Monitor can display a reverse image when in use. ASA has submitted this under recall 19E009. 				Ionitor can display a reverse
	-Units not inc	cluded in reca	ll are not exp	eriencing rev	verse image.
	-The scope is	under review	and will be	amended onc	e finalized.
Production Dates :	JUL 21, 2017	- FEB 28, 201	9		
VIN Range 1:	Begin :	NR	End :	NR	Not sequential
Vehicle Type : Body Style : Power Train : Descriptive Information : Production Dates :	OTHER DIESEL -It has been d Magnitude, O image when i -Units not inc -The scope is	liscovered tha mni Motorho in use. ASA ha cluded in recal under review	t on Certain mes, the Voy s submitted Il are not exp r and will be	ager Mirror M this under rec periencing rev	Ionitor can display a reverse call 19E009. rerse image.
VIN Range 1:		NR	End:	NR	Not sequential
_					
Vehicle 3 ·	2018-2019 M	lagnitude ALL			



Number of potentially involved :

Estimated percentage with defect : 100~%

Population :

19V-240

Part 573 Safety Recall Report

Vehicle Type :		UM & HEAVY	VEHICLES		
Body Style :					
Power Train :				MV 0010/00	10 Chatan Frank Winds
	: -It has been discovered that on Certain MY 2018/2019 Chateau, Four Winds, Magnitude, Omni Motorhomes, the Voyager Mirror Monitor can display a rever image when in use. ASA has submitted this under recall 19E009.				
	-Units not inc	luded in reca	ll are not exp	periencing rev	verse image.
	-The scope is	under reviev	v and will be	amended on	ce finalized.
Production Dates :	JUL 21, 2017	- FEB 28, 201	.9		
VIN Range 1:E	egin :	NR	End :	NR	☐ Not sequential
Vehicle 4 : Vehicle Type : Body Style : Power Train :	OTHER		VEHICLES		
		mni Motorho	omes, the Voy	ager Mirror I	Monitor can display a reverse
	-Units not inc	luded in reca	ll are not exp	periencing rev	verse image.
	-The scope is	under reviev	v and will be	amended on	ce finalized.
Production Dates :	JUL 21, 2017	- FEB 28, 201	.9		
VIN Range 1: B	egin :	NR	End :	NR	☐ Not sequential
Description of Defect : Description of the Defec	t: The VOM?	74MM mirror	r monitor (if	the serial nun	nber starts with A, B, or C) may
-	power ON	with an ima	ge that is rev	ersed from w	hat is expected.
FMVSS					
FMVSS 2	2: NR				
Description of the Safety Risl		vrong directio			the driver may inadvertently nd the vehicle, increasing the
Description of the Cause		or monitor is l ne image disp	0	ult factory set	tings, causing the monitor to

The information contained in this report was submitted pursuant to 49 CFR §573

Supplier Identification :

Component Manufacturer

Name : ASA Electronics Address : 2602 Marina Drive Elkhart INDIANA 46514 Country : United States

Chronology:

12/13/2018 ASA Electronics confirmed the first incident of a reverse image being displayed.

3/18/2019 ASA notified TMC of recall 19E-009 that ASA submitted.

3/22/2019 After discussions with ASA, it was determined that TMC will be handling all recall notifications and reporting and all expenses related to this recall will be charged back to the vendor.

3/25/2019 Engineering has confirmed that there is about a 2 volt drop upon the engine starting in our products.

3/27/2019 TMC's Safety Committee Team agreed that a recall would be issued and a 573 submitted without scope and once we were sure of the scope, we will amend.

escription of Remedy :	
Description of Remedy Program :	TMC, with ASA's cooperation, will provide a harness to install that will prevent the image from inverting. Reimbursement will be provided through the normal warranty claim process, which will be sent as a vendor charge back to ASA.
How Remedy Component Differs from Recalled Component :	Remedy component will not experience an inverted image.
dentify How/When Recall Condition was Corrected in Production :	NR
Recall Schedule :	
Description of Recall Schedule :	TMC will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.
Planned Dealer Notification Date :	MAY 27, 2019 - MAY 27, 2019
Dlammad Originar Natification Data	MAY 27, 2019 - MAY 27, 2019

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573