

Part 573 Safety Recall Report

19V-254

Manufacturer Name : Blanchat Mfg., Inc.**Submission Date :** MAR 28, 2019**NHTSA Recall No. :** 19V-254**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Blanchat Mfg., Inc.

Address : 10 NW 92 Rd.

PO Box 444 Harper KS 67058

Company phone : 620-896-7145

Population :

Number of potentially involved : 1

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2018 Ford F-550 B-27 Minuteman

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : The recall population was determined by reviewing purchase orders to Whelen for part PSR00XRR during their specified production time for their recall. Only two (2) items were ordered during this time period.

Production Dates : NOV 01, 2017 - MAY 16, 2018

VIN Range 1 : Begin : 1FD0W5HY3JEB73730 End : 1FD0W5HY3JEB73730 Not sequential**Description of Defect :**

Description of the Defect : The brake light may activate if there is transient voltage on the brake input line (e.g., without further brake input), but can be returned to normal operation when a brake input is applied and then removed. Whelen determined that the root cause of this condition was tied to transient voltage on the brake input line creating a false and steady activation of the brake light. The condition is dependent on the specific wiring of the vehicle and other equipment installed. The product functions normally if it is not exposed to these specific conditions.

FMVSS 1 : 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2 : NR

Description of the Safety Risk : The brake light may activate if there is a transient voltage on the brake input line (e.g., without further brake input), but can be returned to normal operation when a brake input is applied and then removed.

Description of the Cause : Transient voltage on the input line.

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Whelen Engineering
Address : 51 Winthrop Rd.
Chester CONNECTICUT 06475
Country : United States

Chronology :

On March 19, 2019 Blanchat Mfg., Inc. was notified by NHTSA regarding the recall notice from Whelen. Blanchat Mfg., Inc. notified customers with the recalled product. On March 28, 2019 Blanchat Mfg., Inc. filed the Defect and Noncompliance Information Report with NHTSA as required.

Description of Remedy :

Description of Remedy Program :	Blanchat Mfg., Inc. will, upon request immediately provide a free replacement product and support services to all customers affected by the recall.
How Remedy Component Differs from Recalled Component :	The remedy product has the following distinguishing characteristic versus the recalled product: -Part number revision letter printed on label (permanently applied to rear of product) incremented (e.g. 01-066E957-RB D changed to 01-066E957-RB E) on PSR00XRR
Identify How/When Recall Condition was Corrected in Production :	On product PSR00XRR purchased/installed after May 16, 2018, Whelen has corrected the issue with an update that makes this product immune to the transient voltage issue.

Recall Schedule :

Description of Recall Schedule : All recall notifications have been issued as of March 28, 2019.
Planned Dealer Notification Date : NR - NR
Planned Owner Notification Date : MAR 28, 2019 - APR 05, 2019

* NR - Not Reported