

## View Message

<b>Sent on</b>	04	12	2019	<b>Expires on</b>	05	12	2019
<b>From</b>	Parts and Service Division						
<b>Subject</b>	Information for SB19-019: MDX Lid Light Safety Recall Bulletin						

**PRIORITY/ACTION REQUIRED**

To: All Acura Service Managers  
From: Technical Research and Support Group  
Re: Information for SB 19-019: MDX Lid Light Safety Recall Bulletin

Print this *iV* message and provide a copy to the Shop Foreman and all Service Advisors.

Dear Service Manager,

As you are aware, your dealership has been provided with a quantity of (2) MDX Inner Taillight Jig Sets (Special Tool kits: Part Number 07AAG-TZ5A100) for Service Bulletin 19-019, Safety Recall for the 2014-2019 MDX Inner Taillight(s) to repair or replace the Rear Inner Taillight Assemblies.

Should you require additional Service Kits, they are available for purchase by contacting Honda/Acura INSC at 800-346-6327 with a valid business justification.

Thank you.