

CUSTOMER SERVICE

2014-2015 MY F-TYPE SAFETY RECALL H208



- Certain F-TYPE 2014 and 2015 model year vehicles, previously remedied in recall J047, may have had a seat belt service part installed containing the same defect as the parts from the original recall.
- Due to a catalogue error, service replacement seat belts may not have been correctly wired which can result in the front passenger air bag remaining activated, even when a child restraint is placed in the front passenger seat or a small statured adult occupies that seat. In the event of a crash the seat occupant may be at an increased risk of injury.
- All affected vehicles will be inspected and if required the seat belt tension harness wiring will be modified.
- 7060 USA vehicles will require inspection. Of these approx 125 vehicles may require a wiring modification.
- Recall defect report submitted to **NHTSA April 25th 2019**
- Retailer Notification Bulletin **May 9th 2019**. Technical bulletin expected by **May 20th 2019**
- Customer mailing notification before **June 21st 2019**

