

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS5059  
URGENT - DISTRIBUTE IMMEDIATELY

Date: May 31, 2019

Subject: N182206311-01 - Safety Recall  
Diesel Engine-Block Heater Cord  
Revised Service Procedure

Models: 2017 – 2019 Chevrolet Silverado 2500/3500  
2017 - 2019 GMC Sierra 2500/3500  
2019 Chevrolet Silverado 4500/5500/6500 Medium Duty  
Equipped with Duramax diesel 6.6 liter engine (RPO L5P or L5D) and  
optional engine-block heater cord (RPO K05)

To: All General Motors Dealers

This bulletin has been revised to add the service procedure for 2019 Chevrolet Silverado 4500/5500/6500. Please discard all previous copies of bulletin N182206311.

**Caution: There are two separate procedures for the Silverado/Sierra 2500/3500 and the Silverado 4500/5500/6500 trucks. The procedures are NOT interchangeable between the two. Irreparable damage may be caused to the 4500/5500/6500 vehicle wiring harness if the proper procedure is not performed.**

END OF MESSAGE  
GLOBAL SAFETY FIELD INVESTIGATIONS