

SAFETY RECALL LAUNCH STATUS

N333, N335 & N336



RECALL N333 - DRIVER SEAT BELT EMERGENCY LOCKING RETRACTOR		RECALL N335 - DOORS MAY NOT LATCH OR MAY OPEN WHILE DRIVING		RECALL N336 - VEHICLE DOOR MAY NOT LATCH	
AFFECTED MODELS	16&17 MY RANGE ROVER RANGE ROVER SPORT	AFFECTED MODELS	13-16 MY RANGE ROVER, 14-16 MY RANGE ROVER SPORT	AFFECTED MODELS	16MY RANGE ROVER, RANGE ROVER SPORT
USA VOLUME CANADIAN VOLUME	16,186 1,455	USA VOLUME CANADIAN VOLUME	65,387 ZERO	USA VOLUME CANADIAN VOLUME	28,679 ZERO
REPAIR	INSPECT/REPLACE DRIVER SEAT BELT ASSEMBLY	REPAIR	UPDATE MODULE SOFTWARE & CHECK LATCH FUNCTIONS	REPAIR	REPLACE BOTH LEFT HAND SIDE DOOR LATCHES
REPAIR TIME	c. 20 MINS	REPAIR TIME SOFTWARE	c.20 MINS FOR SW 0.9 HRS- 3.8 HRS FOR LATCH CHECKS MODIFICATIONS	REPAIR TIME	BETWEEN 1.6 and 2.1 HOURS
EXPECTED DATE FOR LAUNCH OF REPAIR PROCESS	AUG 1st 2019	EXPECTED DATE FOR LAUNCH OF REPAIR PROCESS	JULY 18th 2019	EXPECTED DATE FOR LAUNCH OF REPAIR PROCESS	EST. OCT 2nd 2019
CUSTOMER NOTIFICATION BY MAIL	JUNE 27th 2019 (INTERIM)	CUSTOMER NOTIFICATION BY MAIL	JULY 19th 2019	CUSTOMER NOTIFICATION BY MAIL	JULY 19th 2019 (INTERIM)