

# Part 573 Safety Recall Report

# 19V-357

**Manufacturer Name :** Lance Camper Manufacturing, Corp.

**Submission Date :** MAY 10, 2019

**NHTSA Recall No. :** 19V-357

**Manufacturer Recall No. :** NR



## Manufacturer Information :

**Manufacturer Name :** Lance Camper Manufacturing, Corp.

**Address :** 43120 Venture Street

Lancaster CA 93535

**Company phone :** 661-949-3322

## Population :

**Number of potentially involved :** 115

**Estimated percentage with defect :** 75 %

## Vehicle Information :

**Vehicle 1 :** 2019-2020 Lance Truck Camper 855S

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** Products in the recall population have a void between the edge of the fold down bunk bed framing and the window located next to the bunk bed. Products not affected by this recall either do not have a dinette area bunk bed feature or do not have a window located next to the bunk bed.

**Production Dates :** MAR 08, 2019 - MAY 06, 2019

**VIN Range 1 : Begin :**

NR

**End :** NR

☐ Not sequential

**Vehicle 2 :** 2019-2020 Lance Tuck Camper 1172

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** Products in the recall population have a void between the edge of the fold down bunk bed framing and the window located next to the bunk bed. Products not affected by this recall either do not have a dinette area bunk bed feature or do not have a window located next to the bunk bed.

**Production Dates :** MAR 04, 2019 - MAY 06, 2019

**VIN Range 1 : Begin :**

NR

**End :** NR

☐ Not sequential

**Description of Defect :**

Description of the Defect : On truck campers affected by this recall, when the fold down bunk bed is deployed in a sleeping position, there is a void between the edge of the bunk bed framing and the window located next to the sleeping area. In certain cases, this void is large enough to where a child/person could become partially lodged or stuck between the bed frame and the window.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A child/person could potentially become lodged or stuck in the void between the fold down bunk bed frame and the window which may result in injury, suffocation, or death.

Description of the Cause : When the fold down bunk is deployed in a sleeping position, the bed frame is mounted in such a way to not interfere with the window, valance, or shade. Due to circumventing this interference, a void between the fold down bunk bed frame and the window is created.

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

04/29/2019: Lance Camper management received a customer letter alleging that their grandchild had become lodged between the fold down bunk frame and the window and an investigation was launched to look into this incident.

05/06/2019: Executives from REV Group and Lance Camper met to discuss the incident in the customer letter and the results of the investigation.

05/06/2019: Senior Executives of REV Group decided to declare a voluntary safety recall of certain Lance Truck Campers manufactured between 03/08/2018 and 05/06/2019.

**Description of Remedy :**

Description of Remedy Program : Lance Camper will follow up with a recommended solution as soon as the best option is identified.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : Dealer notifications will be conducted via email and Lance Camper Dealer Portal.  
Owner notifications will be conducted via US mail

Planned Dealer Notification Date : JUL 01, 2019 - JUL 06, 2019

Planned Owner Notification Date : JUL 01, 2019 - JUL 06, 2019

\* NR - Not Reported