

SAFETY RECALL LAUNCH STATUS

N333 DOORS MAY NOT LATCH



RECALL N335 - DOORS MAY NOT LATCH OR MAY OPEN WHILE DRIVING	
AFFECTED MODELS	13-16 MY RANGE ROVER, 14-16 MY RANGE ROVER SPORT
USA VOLUME AFFECTED	65,387
REPAIR	UPDATE MODULE SOFTWARE
REPAIR TIME	18 mins for test and sw update. c.0.8 hrs per latch if modification reqd.
REPAIR LAUNCHED	JULY 22nd 2019
CUSTOMER NOTIFICATION BY MAIL	JULY 22nd 2019

Initial Feedback from Technicians in TA cases has identified some concerns when conducting the recall procedure

1. On some vehicles SDD identifies incorrect fuse to connect test tool.
2. PSC700S Battery maintainer voltage exceeds test tool operating range.

SSM 74498 with containment actions issued 7/26/19. Solutions to items 1 and 2 included in an SDD update to be launched Tuesday August 6th.

3. Incomplete module programming step reported on 5 TA cases. Under investigation with Engineering with update expected Tuesday August 6th.

