News Channel Update |

Vehicle Compliance & Analysis

TO: Mercedes-Benz Dealer Principals, General Managers, Sales Managers,	FROM: Gregory Gunther, Department Manager, Vehicle Compliance and
Service Managers, Parts Managers	Analysis, Engineering Services
RE: Recall Campaign Launch Notification	
Replace Passenger-side Airbag (PSAB) Module	DATE: August 14, 2019
MY20 167 (GLE-Class)	

IMPORTANT RECALL CAMPAIGN UPDATE

Please see the attached documents related to the campaign listed above.

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES.

Sincerely,

Gregory Gunther

Department Manager, Vehicle Compliance & Analysis



News Channel Update |

Vehicle Compliance & Analysis

Recall Campaign Launch Notification		ch Notification	August 14, 2019		
Campaign No.:	NHTSA ID	Campaign Desc. :	Deplese DCAD Medule		
2019070011	19V458	19P9193001	Replace PSAB Module		
	recall campaign will l		he passenger airbag on <u>11</u> Model Year ("MY") 2020 GLE-Class (167 gov website and may generate questions from customers. Affected 'EN" on August14, 2019.		
		Backgrou	ınd		
Issue		Daimler AG, the manufacturer of Mercedes-Benz vehicles, has determined that on certain Mode Year ("MY") 2020 GLE-Class vehicles (167 platform), the timing of and/or deployment of the passenger airbag might not meet specifications. At extreme temperatures in the passenge compartment (over +85°C/ 185°F) there may be a delay in the deployment of the airbag or it may not completely deploy. In the event of a crash where the passenger airbag is activated, the performance of the airbag might be impaired. This might lead to an increase risk of injury for the front passenger.			
What We're Doing		MBUSA will conduct a voluntary recall. An authorized Mercedes-Benz dealer will replace the front passenger airbag module on the affected vehicles.			
Parts	ts Parts are available and can be ordered as necessary.				
		Vehicles Aff	ected		
Vehicle Model Year(s)		2020	2020		
Vehicle Model		GLE-Class			
		Vehicle Popu	lations		
Total Recall Population		11	11		
Total Vehicles in Dealer	Inventory	1			
covered by this notifica and Work Instru Loaner and demonstra pro	ation until the vehic uctions will be avai ator vehicles may co ocess, please check notice, it is <u>a viola</u>	cle has been repaired. Once to lable in Star TekInfo Once the ontinue to be driven, but must for other repair measures w	lease any new MY20 GLE-Class vehicles in dealer inventory the remedy is available, the vehicles will be flagged as "OPEN" e repair is complete, the vehicle may be sold or leased. It not be retailed until repaired. As a matter of normal service which might be applicable to the vehicle(s) Internal companies to rent new MY20 GLE-Class vehicles covered sicle has been repaired.		
		Next Steps/	Notes		
Customer Notification T	Customer letters will not be mailed for this topic since none of the affected vehicles have been retailed to customers.		·		
AOMS/SOMS		AOMs – This recall may ger your dealers ASAP.	AOMs – This recall may generate questions from your dealers. Please forward this notice to your dealers ASAP.		
Rental Fleet Partners		This recall may affect vehicles in your fleet. Please contact your respective MBUSA fleet representative for further information and next steps. For repairs, please contact your preferred MBUSA dealer.			
			maintain a high level of vehicle quality and customer satisfaction. ssistance Center at 1-800-FOR-MERCEDES.		



Recall Campaign Bulletin



Campaign No. 2019070011, August 2019

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model GLE-Class vehicles (167 platform)

Model Year 2020

PSAB Incomplete Deployment

Daimler AG, the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2020 GLE-Class vehicles (167 platform), the timing of and/or deployment of the passenger airbag might not meet specifications. At extreme temperatures in the passenger compartment (over +85°C/185°F) there may be a delay in the deployment of the airbag or it may not completely deploy. In the event of a crash where the passenger airbag is activated, the performance of the airbag might be impaired. This might lead to an increase risk of injury for the front passenger. An authorized Mercedes-Benz dealer will replace the front passenger airbag module on the affected vehicles.

Prior to performing this Recall Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired. Always Check VMI for any open campaigns, and perform accordingly.
- Please review the entire Recall Campaign bulletin and follow the repair procedure exactly as described.

Please note that Recall Campaigns do not expire and may also be performed on a vehicle with a vehicle status indicator.

Approximately 11 vehicles are involved.

Order No. P-RC-2019070011

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Before beginning work, **no SRS fault message** may be **present** in the instrument cluster.

If a SRS fault message is present before beginning work, it must be rectified. The fault rectification may not be invoiced together with the recall.

Work procedure

- 1. Disconnect ground line from the on-board electrical system battery.
- 2. Replace front passenger airbag (AR91.60-P-0664ME).
- **3.** Connect ground line to on-board electrical system battery.
- **4.** Switch ignition to position 1. To do so, press start button once without touching the brake pedal. Check if the airbag indicator lamp (**A, Figure 1** *or* **2**) goes off permanently after a few seconds.
- The SRS check after airbag replacement verifies correct installation.





Figure 1 Figure 2

Primary Parts Information

Qty.	Part Name	Part Number	Estimated Replacement Rate
1	Front passenger airbag	A 167 860 78 01	100%

Warranty Information

Operation: Replace front passenger airbag (02-1132)

Includes: Disconnect and connect ground line of on-board electrical system battery.

Damage Code	Operation Number	Labor Time (hrs.)
91 930 01 7	02-1132	1.0

i Note

Operation Number labor times are subject to change.