



**Ditch  
Witch**<sup>®</sup>

Publication Number: ID0568814

Publication Date: June 2019

## Safety Notice

<b>Affected Models</b>	VT9, VT12, VT14, VT17, VT20 & VT24 trailers (carrying HX30, HX50, HX75 machines)
<b>Attention</b>	Dealership Owners, Managers, Parts and Service Managers
<b>What Dealer Should Do</b>	<ol style="list-style-type: none"><li>1. Read the attached customer notice.</li><li>2. Check safety notification search tool on Dealer Central to see a list of units in your area.</li><li>3. Schedule appointments with customers.</li><li>4. Use kits sent to your dealerships to update machines.</li><li>5. File warranty claims.</li></ol>
<b>Parts Required</b>	VT trailer terminal kit (190-2482)  installation also requires universal hand crimp tool (p/n 259-511)
<b>Estimated Repair Time</b>	2 hours
<b>Compensation</b>	parts, labor and mileage
<b>Dealership Notes</b>	<p>URGENT: Please perform this update as soon as possible in the interest of safety. Ditch Witch requests that you update all machines in your area by 12/31/2020.</p> <p>A notification has been mailed to owners of affected models. Please note "What You Should Do" section of the attached customer notice. If you have any questions, contact the Trenchless Product Support Group.</p>