

**CONDITION OF CONCERN**

In the subject vehicles, continued exposure to high levels of absolute humidity may cause the passenger frontal air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the passenger frontal air bag. An inflator rupture could result in metal fragments striking the front passenger or other vehicle occupants, resulting in serious injury or death.

Dealers are to replace the passenger side frontal air bag inflator of subject vehicles with a permanent remedy one.

**MANDATORY AIR BAG INFLATOR RETURN**

The original air bag inflator(s) should be returned by your dealership every 30 days or once 200 inflators have been accumulated. All inflator part numbers can be counted and shipped together for these returns. To schedule a return, please contact XPO at (877) 650-3476. Detailed air bag inflator return instructions can be found on MGSS and the Dealer Assistance Group websites. Failure to return the original inflator will result in a Warranty Claim Debit.

**SUBJECT VEHICLES**

- **Zones A, B and C**

Model	Note
2003-2008 Mazda6, 2006-2007 Mazdaspeed6, 2004-2006 MPV 2004-2011 RX-8	Originally sold or ever registered in Hawaii, California, Texas, Louisiana, Mississippi, Alabama, Georgia, Florida, South Carolina

- **Zone B**

Model	Note
2003-2008 Mazda6, 2006-2007 Mazdaspeed6, 2004-2006 MPV 2004-2011 RX-8	Originally sold or ever registered in Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, West Virginia

- **Zone C**

Model	Note
2003-2008 Mazda6, 2006-2007 Mazdaspeed6, 2004-2006 MPV 2004-2011 RX-8	Originally sold or ever registered in Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, Wyoming

**OWNER NOTIFICATION**

Mazda will notify U.S. owners by first class mail beginning **July 6, 2018** and **RX-8 owners on July 9, 2019**.

**PARTS INFORMATION**

Description	Part Number	Quantity	Applicable Model
Passenger Side Front Airbag Inflator	GJYB-57-K80	1	Mazda6, Mazdaspeed6, MPV
Passenger Side Front Airbag Inflator	F1Z2-57-K80	1	2004-2005 Mazda RX-8
Passenger Side Front Airbag Module assembly with Inflator	FEZ8-57-K70	1	2006 – 2011 Mazda RX-8
Campaign Label	9999-95-065A-06	1=50 labels	<i>Obtain in MStore (no charge)</i>

**WARRANTY CLAIM PROCESSING INFORMATION**

	Mazda6, Mazdaspeed6	MPV	2004-2005 Mazda RX-8 (Inflator)	2006-2011 Mazda RX-8 (Module)
Warranty Type	R	R	R	R
Process Number	AJ043A	AJ043A	AJ043A	AJ043A
Symptom Code	99	99	99	99
Damage Code	99	99	99	99
Part Number Main	GJYB-57-K80	GJYB-57-K80	F1Z2-57-K80	FEZ8-57-K70
Quantity	1	1	1	1
Labor Operation Number	XXP7AXRX	XXP7AXRX	XXP7AARX	XXP7ABRX
Labor Hours	0.5 hrs.	0.6 hrs.	0.6 hrs.	0.4 hrs.

**RENTAL CAR INFORMATION**

Mazda recommends the usage of the MCVP loaner vehicle when available. If all MCVP loaner vehicles are in use and unavailable, and the customer needs a rental car, then use your local rental facility and offer a rental car. Be sure that every effort is made to repair the car within one business day or less in order to allow the next customer the same experience.

**Rental Car Warranty Claim Information**

	<b>MCVP Vehicle Preferred</b>	<b>Rental Agency Vehicle</b>
Warranty Type Code	N/A MCVP does not require claim submission	<b>A</b>
Symptom Code		99
Damage Code		99
Part Number Main Cause		<b>5555-26-18FR</b>
Part Quantity		0
Labor Operation Code		MM024XRX
Labor Hours		0
Sublet – Rental Car		
Sublet Invoice Number		Number from Rental Invoice or Dealer Purchase Order
Sublet Type Code		Enter “Z9” (other)
Sublet Amount		Up to \$30.00 per day for the number of days customer had rental car
Sublet Text		Number of days rental car was supplied to customer

Rental expenses exceeding the two-day limit will require prior DSM Authorization, as outlined in the Mazda Rental Car Reimbursement Program policy.