



SUBJECT:19V-588

- SUBJECT:** Suspension Shackle Replacement
- APPLIES TO:** 2015 – 2019 Pinecrest, Vilano, and Beacon 5th Wheels with 2.25” Shackles
- CONDITION:** An incorrect size suspension link manufactured by Lippert Components, Inc., known as a shackle, can fail prematurely.
- CORRECTION:** Replace all 2.25” (measured hole-center to hole-center) Shackles with 3.13” Shackles

PLEASE READ THE ENTIRE BULLETIN BEFORE PROCEEDING WITH ANY WORK. CONTACT VANLEIGH RV IF THERE ARE ANY CONCERNS WITH THE PROCEDURES CONTAINED IN THIS DOCUMENT.

PART/SERVICE INFORMATION:

Labor Time: 1.0 hours

Qty.	Part Number	Description
1	CCD-0003383	Shackle Link replacement procedure
1	146298	Kit – replacement shackles and fasteners

Note: Safety glasses and all proper safety equipment are required to complete this process.