

# SAFETY RECALL LAUNCH STATUS

## N336 & NEW RECALL N367



RECALL N336 - VEHICLE DOOR MAY NOT LATCH	
AFFECTED MODELS	16MY RANGE ROVER, RANGE ROVER SPORT
USA VOLUME AFFECTED	28,679
REPAIR	TBD-UNDER REVIEW
REPAIR TIME	BETWEEN 1.6 and 2.1 HOURS
EXPECTED DATE FOR LAUNCH OF REPAIR PROCESS	October 2nd 2019
CUSTOMER NOTIFICATION BY MAIL	JULY 19th 2019

RECALL N367 – PARKING CAMERA SYSTEM STABILITY	
AFFECTED MODELS	18 MY RANGE ROVER 18 MY RANGE ROVER SPORT
USA VOLUME AFFECTED	14,277
REPAIR	UPDATE SOFTWARE
REPAIR TIME	TBD
REPAIR LAUNCHED	TBD
CUSTOMER NOTIFICATION BY MAIL	OCTOBER 14TH 2019

