

# SAFETY RECALL LAUNCH STATUS

## N336 & N367 USA MARKET ONLY



RECALL N336 - VEHICLE DOOR MAY NOT LATCH	
AFFECTED MODELS	16MY RANGE ROVER, RANGE ROVER SPORT
USA VOLUME AFFECTED	28,679
REPAIR	REPLACE LEFT SIDE DOOR LATCHES – Potentially RFA software.
REPAIR TIME	BETWEEN 1.6 and 2.1 HOURS
EXPECTED DATE FOR LAUNCH OF REPAIR PROCESS	October 2nd 2019
CUSTOMER NOTIFICATION BY MAIL	JULY 19th 2019

RECALL N367 – PARKING CAMERA SYSTEM STABILITY see bulletin NAS 19.09.001	
AFFECTED MODELS	18 MY RANGE ROVER 18 MY RANGE ROVER SPORT vehicles with surround camera
USA VOLUME AFFECTED	14,289
REPAIR	UPDATE IMC SOFTWARE
REPAIR TIME	0.5 HRS
REPAIR LAUNCH	9/16/2019
CUSTOMER NOTIFICATION BY MAIL	Before OCTOBER 14TH 2019