



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

September 26, 2019

Mr. Nick Aplin
Subaru of America, Inc.
One Subaru Drive
Camden, NJ 08103

NEF-150JK
19V-664

Subject: Loose or Missing Brake Pedal Mounting Bracket Bolt

Dear Mr. Aplin:

This letter serves to acknowledge Subaru of America, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

SUBARU/LEGACY/2020
SUBARU/OUTBACK/2020

Mfr's Report Date: September 18, 2019

NHTSA Campaign Number: 19V-664

Components:

SERVICE BRAKES, HYDRAULIC:PEDALS AND LINKAGES

Potential Number of Units Affected: 3,467

Problem Description:

Subaru of America, Inc. (Subaru) is recalling certain 2020 Outback and Legacy vehicles. The brake pedal mounting bracket may have a missing or insufficiently tightened bolt.

Consequence:

A missing or loose bolt may cause the brake pedal mounting area to deform over time, which can reduce braking performance and increase the risk of a crash.

Remedy:

Subaru will notify owners, and dealers will inspect the brake pedal mounting bracket hardware and replace the hardware or brake pedal assembly, as necessary, free of charge. The recall is expected to begin October 1, 2019. Owners may contact Subaru customer service at 1-844-373-6614. Subaru's number for this recall is WUL-97.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received Subaru's proposed owner notification letter and have approved it for distribution.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov. We look forward to working with you.

Sincerely,



Joshua Neff
Chief, Recall Management Division
Office of Defects Investigations
Enforcement