OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

# 19V-690

Manufacturer Name: Jayco, Inc.
Submission Date: OCT 01, 2019
NHTSA Recall No.: 19V-690
Manufacturer Recall No.: NA



#### **Manufacturer Information:**

Manufacturer Name: Jayco, Inc.

Address: 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone: 800-283-8267

# **Population:**

Number of potentially involved : 446 Estimated percentage with defect : 100 %

#### **Vehicle Information:**

Vehicle 1: 2019-2020 Class C motorhome Redhawk SE

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : Power Train : NR

Descriptive Information: GM Recall - 2019 Chevy 4500 chassis N192264500 - Listing of the recalled Chevy

Chassis VINS were matched to Jayco product serial numbers to create scope of

affected units. 2019 Redhawk SE: K1GA0196-0244 K1GJ0199-0248 K1GN0089-0140 2020 REDHAWK SE L1GA0051-0141 L1GJ0051-0169 L1GN0065-0107

Production Dates: NOV 30, 2018 - SEP 19, 2019

VIN Range 1 : Begin : NR End : NR Not sequential

# **Description of Defect:**

Description of the Defect: The seatbelt unfastened telltale will not illuminate for approximately 5

seconds, after the ignition is moved to the on or start position.

FMVSS 1: 208 - Occupant crash protection

FMVSS 2: NR

Description of the Safety Risk: During the five second delay, the telltale will not alert the driver that the

driver's seatbelt is unbuckled. If the driver does not buckle the seatbelt, this

could increase the driver's risk of injury in the event of a crash.

Description of the Cause: Programming of the instrument panel cluster (IPC)

Identification of Any Warning NR that can Occur:

# **Supplier Identification:**

# **Component Manufacturer**

Name: GM/Chevy

Address: NR

NR

**Country: United States** 

#### **Chronology:**

9-13-2019 Jayco Compliance received copy of GM Document 5403212 regarding a NON-compliance recall N192264500 - regarding the Seatbelt Reminder Telltale Delay on all 2019 Chevy stripped chassis - Production immediately sought location of all products built on the recalled chassis that remained on site in addition to open chassis yet to hit the production line. GM/Chevy was on site  $\,$  9-16-2019 to repair recalled chassis 9-26-19 All details of this Chassis recall were presented to Safety Committee who agreed that a pass through Chassis Recall was required.

#### **Description of Remedy:**

Description of Remedy Program: GM/Chevy service centers will reprogram the instrument panel cluster

(IPC) at no charge to the current owner of the motorhome.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

#### **Recall Schedule:**

Description of Recall Schedule: GM Service Centers will perform the recall remedy and GM will conduct

the recall - sending notifications to retail owners GM will submit

quarterly reports to NHTSA

Jayco will post GM recall information on Jayco RV Dealers website and release recall notification letter to Dealers with affected inventory that

was built on the recalled chassis

Planned Dealer Notification Date: OCT 16, 2019 - OCT 16, 2019 Planned Owner Notification Date: OCT 16, 2019 - OCT 16, 2019

Part 573 Safety Recall Report	19V-690	Page 3
* NR - Not Reported		
The information contained in this report was sub-	mitted pursuant to 49 CFR §573	