

 Tesla, Inc. Service Bulletin		<h2>Replace Driver Sun Visor Due To Missing Labels</h2>	
SB-19-15-003 October 9, 2019			
Classification Recall Bulletin		Section/Group 15 - Interior Trim	Mobile Service Can Perform (where permitted)
Model Year 2019	Model Model 3	Country/Region United States, Canada	Version All
<small>The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.</small>			

Recall Bulletin: Recall Bulletins are mandatory service procedures that must be carried out by Tesla-certified Service Centers. Recall work performed by uncertified technicians could lead to unsafe conditions or voided warranty provisions.

Condition

Some Model 3 vehicles were manufactured without labels on the driver sun visor.

Correction

If the driver sun visor labels are missing (Figures 1 and 2), replace the sun visor with the correct part that contains the labels (Figures 3 and 4).



❌ Figure 1 – Label Missing



❌ Figure 2 – Label Missing



✅ Figure 3 – Label Present



✅ Figure 4 – Label Present

Correction Description	Correction	Time
Inspect Driver Sun Visor; Labels Already Installed	S011915003	0.05
Replace Driver Sun Visor With Correct Part Containing Labels	S021915003	0.10

Part Number	Description	Quantity
Parts Required 1088738-01-I	SUN VISOR ASSEMBLY, LH PROVIDENCE NORTH AMERICA	1

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the [Parts Catalog](#).

Procedure

Inspect the driver sun visor for missing labels:

- If one or both labels are missing (Figures 1 and 2), replace the driver sun visor (refer to Service Manual procedure 15051002).
- If the labels are present (Figures 3 and 4), discontinue this procedure.

