

Recall 185 Dealer Best Practice

Date: October 16, 2019

Attn: Dealer Principal/General Manager/Service Manager/Parts Manager

Subject: Recall 185: 2020MY Elantra BALL JOINT FASTENER TORQUE TSB #19-01-032H (Remedy Available)

<u>Updates To This Document</u>	<u>Date</u>
 Initial Communications: Recall 185: 2020MY Elantra BALL JOINT FASTENER TORQUE TSB #19-01-032H (Remedy Available) 	10/16/19

*** Dealer Stock and Retail Vehicles ***

Dealers must perform this Recall Campaign on all affected vehicles prior to customer retail delivery and whenever an affected vehicle is in the shop for any maintenance or repair.

Affected Vehicles

Hyundai is conducting a safety recall in the United States to inspect and, if necessary, tighten the lower ball joint attachment fasteners on certain model year 2020 Hyundai Elantra vehicles produced between September 4, 2019 through September 10, 2019 by Hyundai Motor Manufacturing Alabama ("HMMA") in the U.S.

The affected vehicles include:

 Certain 2020MY Elantra (ADa) vehicles produced at Hyundai Motor Manufacturing Alabama (VIN beginning with a "5") from September 4, 2019 through September 10, 2019.

Hyundai is initiating this action to ensure the safety and quality of its vehicles and the continued satisfaction of Hyundai customers.

Description

The fasteners securing the ball joints to the lower control arms in the subject vehicles may have been insufficiently tightened during assembly, increasing the risk of ball joint detachment from the lower control arm while driving. A detached lower ball joint while driving could increase the risk of a crash.

Service Action



Reservation – Always check the Vehicle Information Screen in WebDCS for open campaigns and recalls, and advise the customer on time requirements.

Provide customer with transportation options such as an SRC, alternative vehicle, shuttle or rideshare.



Readiness – Review this announcement and the accompanying FAQs with all Service and Parts staff including Reservationist/BDC. Also, complete all applicable training, check your reservation capacity settings (you can set separate capacities for every recall/campaign), confirm email addresses for campaign appointments, and that you have all necessary tools, campaign parts and shop equipment as needed.

Be prepared to put customers in an SRC or alternative transportation if needed.



Reception – Always check the Vehicle Information Screen in WebDCS for open campaigns and recalls, and print a copy for technicians. Provide SRC or an alternative vehicle, as needed. If a customer has declined the campaign, note this on the repair order and request the customer's signature next to the statement.



Repair – Always plug in the GDS before starting the repair. Make sure to complete an MPI on all vehicles and Quality Control your work.

• The front wheels must be removed to gain access to all of the ball joint fasteners.



- Submit claim on Campaign Claim Entry screen
- If a part is found in need of replacement while performing Recall 185 and the affected part is still under warranty, submit a separate claim using the same Repair Order. If the affected part is out of warranty, submit a Prior Approval Request for goodwill consideration prior to performing the work.



Return – Review all completed campaign and repairs to answer any customer questions. Also, schedule the customer's next service



Reconnect – Follow up for customer satisfaction.

Parts

No additional parts are required to complete this recall.

Customer Notification

Hyundai will begin mailing owner notifications by early December 2019.

Thank you for your prompt attention to this important matter and continued commitment to Hyundai customers.

Hyundai Motor America





Customer FAQ

Q1: What is the issue?

A1: The fasteners securing the ball joints to the lower control arms in the subject vehicles may have been insufficiently tightened during assembly, increasing the risk of ball joint detachment from the lower control arm while driving.

Q2: What are the affected vehicles?

A2: Approximately (744) 2020 Hyundai Elantra vehicles produced between September 4, 2019 through September 10, 2019 by Hyundai Motor Manufacturing Alabama ("HMMA") in the U.S.

Q3: What is the safety concern?

A3: Insufficiently tightened ball joint attachment fasteners could increase the risk of ball joint detachment from the lower control arm while driving. A detached lower ball joint while driving could increase the risk of a crash.

Q4: Have there been any accidents or injuries?

A4: Hyundai is not aware of any accidents or injuries related to this condition.

Q5: What will be done during the recall service at the dealer?

A5: Hyundai Motor America plans to notify owners of affected vehicles to return their vehicles to Hyundai dealers to inspect and tighten the ball joint fasteners, if necessary. The procedure will be performed at no charge. Monetary reimbursement to owners for prior related repairs will be made available in accordance with the plan submitted to the agency on May 16, 2018.

Q4: When will owners be notified?

A4: Hyundai will begin mailing owner notifications by early December 2019.





Key Contact Information			
Dealer Support	Contact Information	Description	
Parts	HyundaiPartsHotline@MobisUSA.com 1-800-545-4515	Parts ordering hotline	
Techline	1-800-325-6604	Vehicle Technical Support for Hyundai Dealer Technicians	
Warranty HELPREP Line	1-877-446-2922	Warranty Claim questions for Hyundai Dealers	
Warranty Prior Approval (PA) Center	1-844-371-3808	Warranty Prior Approval (PA) Center for Hyundai Dealers	
Xtime Technical Support	Support@xtime.com 1-866-984-6355	Assistance with Car Care Scheduling: • Appointment / Shop Capacity Management / Campaign Integration / Operation Codes	
AutoLoop Technical Support	Support@autoloop.com 1-877-850-2010	Assistance with Car Care Scheduling: • Appointment / Shop Capacity Management / Campaign Integration / Operation Codes	
CDK Technical Support	https://serviceconnect.support.cdk.com/	Assistance with Car Care Scheduling: • Appointment / Shop Capacity Management / Campaign Integration / Operation Codes	
Customer Support	Contact Information	Description	
Hyundai Customer Care Center (Recall/Campaign Questions)	1-855-671-3059	Customer questions or concerns related to <u>recall or</u> <u>service campaigns</u>	
Hyundai Recall /Campaign Website	www.hyundaiusa.com/recall	Updated information related to the specific recall or service campaign	
Hyundai Customer Care Center (General Questions)	1-800-633-5151	Customers general questions, <u>non-campaign</u> <u>related</u>	
Hyundai Roadside Assistance	1-800-243-7766	Hyundai Roadside Assistance	

Key Reference Information			
Name	Source		
Campaign Central	Consolidated repository of recall and service campaign dealer best practices. Located on the service tab homepage in www.HyundaiDealer.com		
Car Care Scheduling (Xtime) - Tutorials	www.HyundaiDealer.com > Service > Dealer Resources > Documents Library > Car Care Scheduling		
Car Care Scheduling (Xtime) - Recall Appointment Notification	 Log into Xtime Under the menu at the top left, select 'CONFIGURE' Under the dealership tab, click "EMAIL COMMUNICATION" Slide the toggle to "ADVANCED" Populate as many e-mails as desired in the "PARTS DESK EMAIL FIELD" 		
Parts – Campaign Parts Management (CPM) Procedure	As applicable; www.HyundaiDealer.com > Parts > Documents Library > Campaign Parts Management		
Service Rental Car (SRC) Program	www.HyundaiDealer.com > Service tab > SRC Fleet Mgmt Software		
Technical Service Bulletin (TSB)	www.HyundaiDealer.com > Service tab > Hyundai Tech Info		
Uncompleted Campaign VIN Listing	A listing of vehicles is located on WEBDCS> SERVICE tab> select UNCOMPLETED CAMPAIGN VIN LISTING – Dealer Stock (New, SRC, CPO, etc.) and Retailed.		
Recall Campaign Website	www.hyundaiusa.com/recall		
NHTSAWebsite	www.safercar.gov		