



**Date: November 05, 2019**

**Attn: Service Department**

**Subject: Safety Bulletin I-19-03 and Service Advisory ISA-19-03 Released**

**Key Actions & Timing: Please Read**

**Questions: Contact Indian Motorcycle Technical Service**

Dear Indian Motorcycle Dealer,

Please review the following communication that was posted on Tuesday, 11/05/2019.

Indian Motorcycle has determined the gear position switch used on 2014-2019 (111 c.i.) motorcycles may provide an inaccurate signal, which can lead to an incorrect gear being displayed. Oxidation on the contacts of the gear position switch may cause a change in resistance values resulting in the rider display indicating an incorrect gear. Incorrect gear indication during start-up can increase the risk of a crash.

Click [HERE](#) to view I-19-03.

Click [HERE](#) to view ISA-19-03.

Click [HERE](#) to view Dealer FAQs.

Thank you for your attention.

Sincerely,  
Indian Motorcycle Service

This email was sent by Polaris Inc to Steve.Blanchette@polaris.com.

[Privacy Policy](#)

© 2019 Polaris Inc  
2100 Highway 55, Medina, MN 55340, USA | [Polaris.com](#)