

# Part 573 Safety Recall Report

# 19V-786

**Manufacturer Name :** Thor Motor Coach

**Submission Date :** NOV 01, 2019

**NHTSA Recall No. :** 19V-786

**Manufacturer Recall No. :** RC000178



## Manufacturer Information :

## Population :

Manufacturer Name : Thor Motor Coach

Number of potentially involved : 229

Address : PO Box 1486

Estimated percentage with defect : 100 %

701 County Road 15 Elkhart IN 46515

Company phone : 877-500-1020

## Vehicle Information :

Vehicle 1 : 2019-2020 Magnitude BB35, BH35, SV34, XG32

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : -Ford Motor Company has decided that certain vehicles fail to conform to FMVSS 202a for Head Restraints and FMVSS 207 for Seating Systems. Compliance Recall Notice 19C07 / NHTSA Recall 19V-633  
-Remedied products will conform to FMVSS 202a and FMVSS 207.  
-143 Magnitude units are in the recall scope.

Production Dates : NOV 16, 2018 - OCT 16, 2019

VIN Range 1 : Begin : 1FDUF5GT0KDA07079 End : 1FDUF5HTXKEF86171 ☒ Not sequential

Vehicle 2 : 2019-2020 Omni BB35, BH35, SV34, XG32

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : -Ford Motor Company has decided that certain vehicles fail to conform to FMVSS 202a for Head Restraints and FMVSS 207 for Seating Systems. Compliance Recall Notice 19C07 / NHTSA Recall 19V-633  
-Remedied products will conform to FMVSS 202a and FMVSS 207.  
-86 Omni units are in the recall scope.

Production Dates : NOV 16, 2018 - OCT 16, 2019

VIN Range 1 : Begin : 1FDUF5GT0KDA07079 End : 1FDUF5HTXKEF86171 ☒ Not sequential

## Description of Noncompliance :

Description of the Noncompliance : One or more of the seatbacks may have an improperly assembled recliner mechanism.

FMVSS 1 : 202 - Head restraints

FMVSS 2 : 207 - Seating systems

Description of the Safety Risk : A seatback with an improperly assembled recliner mechanism may have reduced strength and may not adequately restrain an occupant in the event of a crash, increasing the risk of injury.

Description of the Cause : NR

Identification of Any Warning that can Occur : NA

## Supplier Identification :

### Component Manufacturer

Name : Ford Motor Company

Address : PO Box 1904  
Dearborn MICHIGAN 48121-1904

Country : United States

## Chronology :

10/28/2019 – TMC received notification from Ford via letter that they have released a safety recall.

10/29/2019 – TMC gathered information regarding scope of TMC motorhomes affected by recall.

## Description of Remedy :

Description of Remedy Program : Ford has authorized dealers to inspect the seat backs and replace if necessary free of charge.

How Remedy Component Differs from Recalled Component : Remedy component will conform to FMVSS 202a and FMVSS 207.

Identify How/When Recall Condition was Corrected in Production : NR

## Recall Schedule :

Description of Recall Schedule : Ford has begun notification to motorhome owners. The recall is being issued to allow owners & dealer to find recall information based upon the final stage manufacturer's name in the event of a search. Ford has issued a recall (19V-633) and their recall will satisfy the regulatory notification requirements for both owners and dealers. Ford will be reporting

Planned Dealer Notification Date : NR - NR  
Planned Owner Notification Date : NR - NR

response rates for their recall and Thor Motor Coach will not be duplicating this reporting.

\* NR - Not Reported