

Classification:  
 BR19-007e

 Reference:  
 ITB19-037e

 COPYRIGHT© NISSAN NORTH AMERICA, INC.  
 Date:  
 September 10, 2020

## VOLUNTARY SAFETY RECALL CAMPAIGN 2017-2019 QX60; ABS ACTUATOR INSPECTION

**CAMPAIGN ID #:** R1917  
**APPLIED VEHICLES:** 2017-2019 QX60 (L50)

**This bulletin has been superseded by ITB19-038.**

Please discard previous versions of this bulletin.

### AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
November 12, 2019	ITB19-037	Original bulletin published
November 13, 2019	ITB19-037a	Email address changed on page 3
December 17, 2019	ITB19-037b	Additional information added to the body of the bulletin
January 17, 2020	ITB19-037c	Changed the ASIST tool name on pages 5, 6, and 10
February 4, 2020	ITB19-037d	Information revised in step 4 on page 4
September 10, 2020	ITB19-037e	Bulletin superseded

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.