

SAFETY RECALL V62-WK WD FUEL PUMP RELAY Parts Information

OVERVIEW

Safety Recall V62-2011-2013 WK WD Fuel Pump Relay is currently in Interim status and the remedy has not yet been defined. This recall is to address relays installed during the R09 or P54 Safety Recall procedure.

In the instance that a customer comes in with a fuel pump relay failure before the V62 Dealer Instructions launch, please follow the below instructions to repair the vehicle.

If the vehicle has not had the RO9 or P54 Safety Recall performed and the VIN is still reported as open in VIP, please order the recall parts per the Dealer Instructions using VIN Specific Parts Ordering and repair the vehicle per the Dealer Instructions. VIN Specific ordering will perform a check and will not allow ordering of the part if the recall is not open.

If the vehicle has had the R09 or P54 Safety Recall completed/closed repair the vehicle using the service part number 56007080AB, as also noted in StarParts.

FCA appreciates your support!