

# Part 573 Safety Recall Report

# 19V-816

**Manufacturer Name :** Newmar Corporation**Submission Date :** NOV 15, 2019**NHTSA Recall No. :** 19V-816**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street  
PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

**Population :**

Number of potentially involved : 6

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2020-2020 Newmar Mountain Aire

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style :

Power Train : NR

**Descriptive Information :** On certain motorhomes, if the headlight high beams are activated, only the high beam bulbs illuminate. The intention of the high beam function is to have both the high beam and low beam bulbs illuminate together. Not having the required illumination of the road could reduce the driver's visibility, which could increase the risk of a crash causing injury and/or damage to property. Correction: Daimler Trucks North America Authorized Service Facilities will repair as necessary to ensure the low beam bulb will turn on along with the high beam bulb.

Production Dates : JUN 05, 2019 - AUG 29, 2019

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

**Description of the Defect :** The intention of the high beam function is to have both the high beam and low beam bulbs illuminate together. Not having the required illumination of the road could reduce the driver's visibility, which could increase the risk of a crash causing injury and/or damage to property.

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** The intention of the high beam function is to have both the high beam and low beam bulbs illuminate together. Not having the required illumination of the road could reduce the driver's visibility, which could increase the risk of a crash causing injury and/or damage to property.

**Description of the Cause :** NR

Identification of Any Warning NR  
that can Occur :

## Supplier Identification :

### Component Manufacturer

Name : NR  
Address : NR  
NR  
Country : NR

## Chronology :

On 11/13/19, it was discovered by a Newmar employee that the high beam did not included the low beam as intended. On 11/15/2019, Newmar is giving notice of defect to NHTSA.

## Description of Remedy :

Description of Remedy Program : Daimler Trucks North America Authorized Service Facilities will repair as necessary to ensure the low beam bulb will turn on along with the high beam bulb. This will be done at no cost to the customer.

How Remedy Component Differs NR  
from Recalled Component :

Identify How/When Recall Condition NR  
was Corrected in Production :

## Recall Schedule :

Description of Recall Schedule : On or before 01/14/2020, customer/dealer letters will be sent out.  
Planned Dealer Notification Date : JAN 14, 2020 - JAN 14, 2020  
Planned Owner Notification Date : JAN 14, 2020 - JAN 14, 2020

\* NR - Not Reported