



July, 2020

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2019 Ranger has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number 19S43 - Rear Tail Lamps and Description:

What is the issue?



On your vehicle, it may be possible that terminals in an inline connector were misaligned during assembly, which may result in a loss of function in both left and right rear tail lamps. In this condition, your vehicle will exhibit a rapidly flashing turn signal indicator on the instrument cluster when your turn signal is used. Your rear tail lamps may not illuminate. This includes the stop, turn, rear position, and backup lamps, which can reduce the vehicle's visibility and may not fully alert other drivers that the vehicle is braking, turning, or reversing, increasing the risk of crash. The center high mounted stop lamp (CHMSL) is not affected. The loss of rear tail lamps could be intermittent.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: www.Fordowner.com. Thank you for your attention to this very important matter.

Julio de, 2020

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2019 Ranger las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: 19S43 - Luces traseras

¿Cuál es el problema?



Es posible que los terminales en un conector en línea de su vehículo hayan sido mal alineados durante el ensamble, lo cual podría traducirse en un pérdida de la función tanto de la luz trasera izquierda como derecha. De esta forma, cuando utilice la señal direccional de su vehículo, el indicador del tablero de instrumentos destellará rápidamente. Las luces traseras podrían no encenderse. Esto incluye luz de freno, direccional, de posición trasera y de retroceso; todo esto reduce la visibilidad del vehículo y podría no alertar del todo a otros conductores que el vehículo está frenando, girando o retrocediendo; esta situación aumenta el riesgo de choque. La tercera luz de freno (CHMSL) no se ve afectada. La pérdida de las luces traseras podría ser intermitente.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: www.Fordowner.com. Gracias por su atenciic en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C


A / 0021 / 000000000000001 / A



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶



▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶