

CAMPAIGN LAUNCH STATUS

N412 RECALL-20MY EVOQUE H270 20MY I-PACE ACOUSTIC ALERTS



SAFETY RECALL N412 EVOQUE HEADLINER	
AFFECTED MODELS	20MY EVOQUE
NAS VOLUME AFFECTED	3444 US + 637 CAN of which 193 are in retailer stock
REPAIR	In temps below 25F, the adhesive bond attaching a metal plate to the headliner may reduce which can cause the plate to detach during an airbag deployment
REPAIR TIME	2 hrs
LAUNCH	Dec 5 th stop sale
Notes	Repair launch date TBC

SERVICE ACTION H270 I-PACE Acoustic Alert System	
AFFECTED MODELS	20MY I-PACE
NAS VOLUME AFFECTED	4637 USA 115 CAN
REPAIR	Affected vehicles require a car configuration file update to prevent a false acoustic warning system error message from displaying.
REPAIR TIME	0.2 hrs
LAUNCHED	Dec 18 th
Notes	