



SIB 65 06 20

2020-02-07

RECALL CAMPAIGNS 19V-852 AND 19V-853: INSPECTION  
PERFORMED AND DRIVER'S FRONT

## RECALL CAMPAIGNS 19V-852 AND 19V-853: INSPECTION PERFORMED AND DRIVER'S FRONT AIR BAG (NADI) INFLATOR NEEDS TO BE REPLACED

### MODEL

E-Series	Model Description	Production Date
E46	3 Series	February 17 1998 – July 14, 2000

### AFFECTED VEHICLES

The recalls involves E46 (3 Series) Vehicles, Model Years from 1999-2001. These vehicles require a new air bag inflator to be installed.

Vehicles which require this Recall Campaign to be completed will show it as Open” when checked either in AIR, the Service Menu of DCSnet (Dealer Communication System), ISPA Next or Warranty Vehicle Inquiry.

### SITUATION

BMW AG is conducting a Voluntary Safety Recall (effective December 4, 2019) on certain Model Year – 1999-2001 BMW vehicles that were produced between February 17, 1998 – July 14, 2000.

**This bulletin is for vehicles which already had the inspection process completed but due to a lack of parts availability, have not yet had a new air bag inflator installed.**

### CAUSE

This recall involves vehicles equipped with the single-stage Takata Non-Azide Driver Inflator (NADI) which may have been produced with an insufficient seal that could allow moisture to enter the inflator.

### CORRECTION

Replace the driver's front air bag inflator.

### PROCEDURE

Currently there are no parts available to make this repair. This bulletin will be updated with repair instructions once parts become available.

### PARTS INFORMATION

Currently there are no parts available to make this repair. This bulletin will be updated with parts information once parts become available.

### WARRANTY INFORMATION

Reimbursement for this Recall will be via normal claim entry utilizing the following information

Defect Code	0032040300	
-------------	------------	--

This bulletin will be updated with warranty information once parts become available.

Copyright ©2020 BMW of North America, Inc.

