



July, 2020

*** * * IMPORTANT SAFETY RECALL REMINDER * * ***

According to our records, your 2020 Explorer has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number 19S49 - Fuel Line Hard Contact
and Description:

What is the issue? On your vehicle, the liquid fuel line may have been assembled with a protective sleeve that is not long enough. This may allow for potential hard contact with the protected vapor fuel line. Over time, the protective sleeve on the vapor fuel line may chafe through the plastic liquid fuel line and cause a fuel leak. A fluid leak at the top of the engine compartment could contact hot engine components, increasing the risk of fire.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: www.Fordowner.com.

Thank you for your attention to this very important matter.

Julio de, 2020

*** * * RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD * * ***

SegUR nuestros registros, no se realizaron en sur 2020 Explorer las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: 19S49 - Contacto violento de la tubería de combustible

¿Cuál es el problema? En su vehículo, la tubería de combustible líquido podría no haberse ensamblado con una manga protectora lo suficientemente extensa. Eso podría permitir un posible contacto violento con la tubería de vapor de combustible protegida. Con el tiempo, la manga protectora en la tubería de vapor de combustible puede atravesar la tubería de combustible líquido de plástico y provocar una fuga de combustible. Una fuga de líquido en la parte superior del compartimiento del motor podría entrar en contacto con los componentes calientes del motor, lo cual aumenta el riesgo de incendio.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: www.Fordowner.com.

Gracias por su atenciic en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

D / 0020 / 00000000000010 / A




SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION





July, 2020

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2020 Aviator has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number 19S49 - Fuel Line Hard Contact
and Description:

What is the issue? On your vehicle, the liquid fuel line may have been assembled with a protective sleeve that is not long enough. This may allow for potential hard contact with the protected vapor fuel line. Over time, the protective sleeve on the vapor fuel line may chafe through the plastic liquid fuel line and cause a fuel leak. A fluid leak at the top of the engine compartment could contact hot engine components, increasing the risk of fire.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: www.Lincolnowner.com.

Thank you for your attention to this very important matter.

Julio de, 2020

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2020 Aviator las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: 19S49 - Contacto violento de la tubería de combustible

¿Cuál es el problema? En su vehículo, la tubería de combustible líquido podría no haberse ensamblado con una manga protectora lo suficientemente extensa. Eso podría permitir un posible contacto violento con la tubería de vapor de combustible protegida. Con el tiempo, la manga protectora en la tubería de vapor de combustible puede atravesar la tubería de combustible líquido de plástico y provocar una fuga de combustible. Una fuga de líquido en la parte superior del compartimiento del motor podría entrar en contacto con los componentes calientes del motor, lo cual aumenta el riesgo de incendio.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: www.Lincolnowner.com. Gracias por su atenciic en este asunto sumamente importante.



THE LINCOLN MOTOR COMPANY

P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C


A / 0001 / 000000000000001 / A



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶



▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶