

Safety Bulletin T-19-02 Released

Dear Polaris Slingshot Dealer,

Please review the following communication that was posted on Thursday, 12/12/2019.

Polaris Slingshot has identified some 2019 vehicles built from 2/12/2019 through 7/31/2019 may have 10A circuit breakers that do not meet quality standards. Affected circuit breakers do not meet functional specifications and may cause an engine to unexpectedly stop running, increasing the risk of a crash.

Click [HERE](#) to view T-19-02.

Thank you for your attention.

Sincerely,  
*Polaris Service*