

Service Bulletin

22-016

What's New

Dana Forward Rear Axle Output Shaft

Section

22 - Rear Axle

Description

Dana Forward Rear Axle Output Shaft

Release Date

12/10/2019

Introduction

Output shafts may not have been correctly heat-treated and may shear near the pinion nut. Dealers are instructed to hold these vehicles. This bulletin will be updated when a repair path is available.

Resolution

Campaign

Service all chassis affected that enter your dealership, even if the customer has no issue with the chassis.

1. Review the attached chassis list for your dealer code and schedule your customer(s) for service if their chassis is on the list.
2. Hold all vehicles found at your dealership.
3. Perform repairs on these vehicles after the bulletin is updated with a repair procedure.



CAUTION

Dealers that release trucks on the chassis list without completing the actions described below may face liability for progressive damage.

Attachments

Chassis List

Authored by: PR
