

IMPORTANT SAFETY RECALL

AUTOCAR, LLC SAFETY RECALL ACTT-2002 NHTSA RECALL NO. 19V922

August 2020

TO: U.S. Distributors

Dealer Principals, Service Managers, Warranty Managers, Parts Managers

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Autocar, LLC has determined that a defect, which relates to motor vehicle safety, exists in 3448, 2015-2020 model year Xspotter chassis. These chassis were manufactured between March 25, 2014 and August 6, 2019 with non-sequential serial numbers in the range of 217590 through 231570. Accordingly, a recall to address this issue is being initiated effective August 27, 2020.

MODELS AFFECTED:	Autocar Xpotter MY 2015-2020
<u>COMPONENTS</u> <u>AFFECTED:</u>	The headlamp relay can become disconnected.
<u>SAFETY DEFECTS</u> AND POTENTIAL RISKS:	If the headlamp relay becomes disconnected during nighttime operation there will be a sudden loss of headlamps, which could result in property damage, personal injury or a crash.
<u>REPAIR</u> <u>REQUIRED:</u>	A fuse box relay retainer will be installed at no charge to the owner.
<u>REPAIR</u> AVAILABLE:	VIN profiles in the Autocar Warranty System will be updated to show the open recall on August 27, 2020 and a spreadsheet of the affected VINs will be available in the Warranty system.
REMINDER:	It is a violation of Federal law to sell or lease a vehicle covered by this recall notice unless the recall remedy has been completed. Substantial civil penalties apply to violations of this law.
	If you have any questions or concerns, please contact the Autocar Warranty Department at warranty@autocartruck.com.
Sincerely,	
AUTOCAR, LLC	

ACF 00002 Rev. 000