

CAMPAIGN LAUNCH STATUS

N454 - SAFETY RECALL 20MY RANGE ROVER EVOQUE - HEADLINER



EQUIPMENT RECALL N454 - INCORRECT SPECIFICATION REPLACEMENT HEADLINER	
AFFECTED MODELS	20MY RANGE ROVER EVOQUE
VEHICLES AFFECTED	2 USA, 1 CAN
REPAIR	Affected vehicles require replacement of the headliner with a correct specification part
REPAIR TIME	4.2 hrs+ drive in/out
CAMPAIGN LAUNCH	06/12/2020

- The 3 affected vehicles have been previously repaired with replacement service parts that have been found to be non-compliant with occupant protection regulations.
- An additional affected part in retailer inventory has been scrapped.
- Vehicles were identified from parts sales and warranty claims.
- Customers were initially notified in May and will receive a further notification on or before the week of July 6th , 2020