OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 20E-085

**Manufacturer Name:** Denso International America, Inc.

**Submission Date :** NOV 24, 2021 **NHTSA Recall No. :** 20E-085

**Manufacturer Recall No.:** NR



#### **Manufacturer Information:**

Manufacturer Name: Denso International America, Inc.

Address: 24777 DENSO Drive

Southfield MI 48033

Company phone: 999

## **Population:**

Number of potentially involved: 2,483,801

Estimated percentage with defect: NR

### **Equipment Information:**

Brand / Trade 1: DENSO

Model: Fuel Pump

Part No.: Various Part Numbers

Size: N/A

**Function:** Fuel Supply

Descriptive Information: The low-pressure fuel pump is located in the fuel tank and supplies fuel pressure

to the fuel injection system.

Production Dates: JUN 26, 2017 - SEP 24, 2019

## **Description of Defect:**

Description of the Defect: For Description of Defect, please see DIR filed April 24, 2020 attached to recall

20E-026.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: For Description of Safety Risk please see DIR filed April 24, 2020 attached to

recall 20E-026.

Description of the Cause: For Description of Cause, please see DIR filed April 24, 2020 attached to recall

20E-026.

Identification of Any Warning For Identification of Any Warning that can Occur, please see DIR filed April 24,

that can Occur: 2020 attached to recall 20E-026.

#### **Involved Components:**

Component Name: NR

Component Description: NR

Component Part Number: NR

## **Supplier Identification:**

#### **Component Manufacturer**

Name: DENSO International America, Inc.

Address: 24777 Denso Drive

Southfield Michigan 48086

**Country: United States** 

## **Chronology:**

See attached file "211124 DENSO DIR Amendment 5 20E-085" for full chronology.

#### **Description of Remedy:**

Description of Remedy Program: The remedy program, if any, will be determined by vehicle manufacturers.

How Remedy Component Differs The impeller of fuel pumps utilized for a remedy component have higher from Recalled Component: density.

Identify How/When Recall Condition NR was Corrected in Production:

#### **Recall Schedule:**

Description of Recall Schedule: The recall schedule will be decided by vehicle manufacturers.

Planned Dealer Notification Date: NR - NR Planned Owner Notification Date: NR - NR

#### **Purchaser Information:**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name: American Honda Motor Co., Inc.

Address: 1919 Torrance Blvd.

Torrance CA 90501-2746

Country: US Company Phone: NR

Name: Ford Motor Company

Address: 1 American Rd

Dearborn MI 48126

Country: US

**Company Phone: 8003923673** 

Name: Mazda North American Operations

Address: 1025 Connecticut Avenue NW

Washington DC 20036

Country: US Company Phone: NR

Name: Mitsubishi Motors North America, Inc.

Address: 4015 Aspen Grove Dr

Franklin TN 37067

Country: US

Company Phone: 8654414166

Name: Subaru of America, Inc.

Address: One Subaru Drive

Camden NJ 08103

Country: US

Company Phone: 8564888500

Name: Toyota Motor North America, Inc.

Address: 6565 Headquarters Drive

Plano TX 75024

Country: US

Company Phone: 4692924000

Name: Magnuson Products, LLC Address: 1990 Knoll Drive, Building A

Ventura CA 93003

Country: US

**Company Phone**: 8056428833

\* NR - Not Reported