

February 6, 2020

Mr. Wayne Gates Hyundai Motor America 10550 Talbert Ave Fountain Valley, CA 92708

Subject: ABS Module May Short Circuit

Dear Mr. Gates:

This letter serves to acknowledge Hyundai Motor America's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: HYUNDAI/ELANTRA/2006-2011 HYUNDAI/ELANTRA TOURING/2007-2011

Mfr's Report Date: February 4, 2020

NHTSA Campaign Number: 20V-061

Components: SERVICE BRAKES, HYDRAULIC:ANTILOCK:CONTROL UNIT/MODULE

Potential Number of Units Affected: 429,686

Problem Description:

Hyundai Motor America (Hyundai) is recalling certain 2006-2011 Elantra and 2007-2011 Elantra Touring vehicles. Moisture may enter the Anti-lock Brake (ABS) Module and result in an electrical short.

Consequence:

An electrical short within the ABS Module may cause an engine compartment fire, even when the car is turned off, increasing the risk of an injury.

Remedy:

Hyundai will notify owners, and dealers will install a relay in the vehicle's main junction box to prevent the risk of an ABS shortcircuit while the car is turned off, free of charge. The recall is expected to begin April 3, 2020. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 188.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150JK 20V-061

Please amend the chronology to include the number of potentially related fires.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov. We look forward to working with you.

Sincerely,

Joshua Neff Chief, Recall Management Division Office of Defects Investigations Enforcement

