

CAMPAIGN LAUNCH STATUS

H283 SAFETY RECALL 10MY XF - FUEL TANK OUTLET FLANGE CRACKING



SAFETY RECALL H283 – FUEL TANK OUTLET FLANGE

AFFECTED MODELS	10MY XF (X250) with 4.2L V8 engines
VOLUME AFFECTED	2,907 USA 79 CANADA All Retailed
REPAIR	Affected vehicles will have the fuel tank outlet flange replaced with a component with revised design
REPAIR TIME	Est 0.8 hrs + DIDO
LAUNCH	Target May 29 th 2020
Notes	Interim customer mailing April 6 th 2020

- On affected vehicles retailer's have reported the fuel tank outlet flange is cracked. This can cause fuel odor, a check engine light and occasionally liquid fuel on the ground.
- Affected vehicles will be repaired with a new flange. Similar to J059 Recall for XF with 5.0L engines
- Retailer notification issued 2/27/20 in bulletin NAS20.02.022
- Parts are currently not available. Expected to be in stock at end of May, 2020.
- Customers were notified mail April 6th 2020 a repair is not available at this time.