

Part 573 Safety Recall Report

20V-156

Manufacturer Name : Daimler Vans USA, LLC**Submission Date :** MAR 18, 2020**NHTSA Recall No. :** 20V-156**Manufacturer Recall No. :** VS3BEGREPP**Manufacturer Information :**

Manufacturer Name : Daimler Vans USA, LLC

Address : One Mercedes-Benz Drive
Sandy Springs GA 30328

Company phone : 854-888-3374

Population :

Number of potentially involved : 332

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2019 Mercedes-Benz Sprinter

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : VAN

Power Train : DIESEL

Descriptive Information : Based on the identification of a production error and analysis of the production information, the affected population was determined to be Sprinter (VS30, Platform 907) for the USA produced from March 8, 2018 to November 24, 2019. Vehicles outside of the scope of the population received an accurate label indicating the spare wheels maximum speed.

Production Dates : MAR 08, 2018 - NOV 24, 2019

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 2 : 2018-2019 Freightliner Sprinter

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : VAN

Power Train : DIESEL

Descriptive Information : Based on the identification of a production error and analysis of the production information, the affected population was determined to be Sprinter (VS30, Platform 907) for the USA produced from March 8, 2018 to November 24, 2019. Vehicles outside of the scope of the population received an accurate label indicating the spare wheels maximum speed.

Production Dates : MAR 08, 2018 - NOV 28, 2019

VIN Range 1 : Begin : NR End : NR

 Not sequential

Description of Defect :

Description of the Defect : Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz and Freightliner vans, has determined that on certain Sprinter vehicles from platform 907 (VS30), the information label indicating the maximum speed was not affixed to the spare wheel.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Without the label, an operator could operate the vehicle in excess of the spare wheel's maximum speed, increasing the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

The chronology is attached as a Miscellaneous Document.

Description of Remedy :

Description of Remedy Program : An authorized Mercedes-Benz or Freightliner Sprinter dealer will attach the speed limitation label on the spare wheel.

Pursuant to 49 C.F.R. § 577.11(e), Daimler Vans does not plan to provide notice about pre-notice reimbursement to owners since all involved vehicles remain covered under the new vehicle warranty.

How Remedy Component Differs from Recalled Component : An authorized Mercedes-Benz or Freightliner Sprinter dealer will attach the speed limitation label on the spare wheel.

Identify How/When Recall Condition was Corrected in Production : Immediately after the situation was identified the vehicles still in factory access were inspected and, if necessary, reworked as part of an internal factory campaign in November 2019. In addition, an additional visual inspection of the labels was introduced in production and employees were retrained on the label inspection process.

Recall Schedule :

Description of Recall Schedule : Dealers will be notified of the pending voluntary recall campaign approx. in April 2020. A copy of all communications will be provided when available. Owners will be notified approximately one week after the recall launches to dealers.

Planned Dealer Notification Date : APR 24, 2020 - APR 24, 2020

Planned Owner Notification Date : MAY 01, 2020 - MAY 01, 2020

* NR - Not Reported