OMB Control No.: 2127-0004

Part 573 Safety Recall Report

20V-166

Manufacturer Name: BMW of North America, LLC

NHTSA Recall No.: 20V-166
Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: BMW of North America, LLC

Address: P.O. Box 1227

Westwood NJ 07675-1227

Company phone: 18005257417

Population:

Number of potentially involved : 365 Estimated percentage with defect : 100 %

Vehicle Information:

Vehicle 1: 2018-2020 BMW RnineT

Vehicle Type: MOTORCYCLES

Body Style :

Power Train: GAS

Descriptive Information: Approximately 108 motorcycles were produced with a brake fluid reservoir cover

which may not fully conform to FMVSS 122 Section 5.1.9(d).

Basis for recall population determination: Motorcycle production records were reviewed to determine the specific Model Year 2018-2020 BMW R nine T motorcycles manufactured from 09/29/2017 through 09/19/2019 with an order option for a

color-specific brake fluid reservoir cover.

Recall component difference to non-recall component: Recall motorcycles were produced with a brake fluid reservoir cover which may not fully conform to FMVSS

122 Section 5.1.9(d).

Production Dates: SEP 29, 2017 - SEP 19, 2019

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2:	2018-2020 BMV	V RnineT Scam	bler		
Vehicle Type :	MOTORCYCLES				
Body Style :					
Power Train :	GAS				
Descriptive Information :	: Approximately 11 motorcycles were produced with a brake fluid reservoir cover which may not fully conform to FMVSS 122 Section 5.1.9(d).				
	Basis for recall population determination: Motorcycle production records were reviewed to determine the specific Model Year 2018-2020 BMW R nine T Scrambler motorcycles manufactured from $02/28/2017$ through $03/02/2020$ with an order option for a color-specific brake fluid reservoir cover.				
	-	n optional bral	o non-recall component: Recall r ke fluid reservoir cover which m	•	
Production Dates :	FEB 28, 2017 - M	IAR 02. 2020			
VIN Range 1:		NR	End: NR	☐ Not sequential	
Vehicle 3:	2018-2018 BMV	V RnineT Racei	r		
	MOTORCYCLES				
Body Style :	WOTOWCTOLLS				
Power Train :					
	: Approximately 24 motorcycles were produced with a brake fluid reservoir cover which may not fully conform to FMVSS 122 Section 5.1.9(d).				
	Basis for recall population determination: Motorcycle production records were reviewed to determine the specific Model Year 2018 BMW R nine T Racer motorcycles manufactured from 12/20/2017 through 02/06/2018 with an order option for a color-specific brake fluid reservoir cover.				
	Recall component difference to non-recall component: Recall motorcycles were produced with an optional brake fluid reservoir cover which may not fully conform to FMVSS 122 Section 5.1.9(d).				
Production Dates :	DEC 20, 2017 - F	EB 06, 2018			
VIN Range 1:		NR	End: NR	☐ Not sequential	

Vehicle 4:	2019-2020 BM	W R1250GS			
	MOTORCYCLES				
Body Style :					
Power Train :					
Descriptive Information :	: Approximately 50 motorcycles were produced with a brake fluid reservoir cover which may not fully conform to FMVSS 122 Section 5.1.9(d).				
	Basis for recall population determination: Motorcycle production records were reviewed to determine the specific Model Year 2019-2020 BMW R 1250 GS motorcycles manufactured from $03/12/2019$ through $11/13/2019$ with an order option for a color-specific brake fluid reservoir cover.				
	-	an optional bra	-	ent: Recall motorcycles were ver which may not fully confor	m to
Production Dates :	MAR 12. 2019 -	NOV 30. 2019			
VIN Range 1:		NR	End: NR	☐ Not sequen	tial
	2019-2020 BM' MOTORCYCLES		venture		
Body Style :					
Power Train:					
	Approximately		were produced wit FMVSS 122 Section	h a brake fluid reservoir cover n 5.1.9(d).	
	Basis for recall population determination: Motorcycle production records were reviewed to determine the specific Model Year 2019-2020 BMW R 1250 GS Adventure motorcycles manufactured from $02/13/2019$ through $02/10/2020$ with an order option for a color-specific brake fluid reservoir cover.				
	Recall component difference to non-recall component: Recall motorcycles were produced with an optional brake fluid reservoir cover which may not fully conform to FMVSS 122 Section 5.1.9(d).				
Production Dates :	FEB 13, 2019 - 1	FEB 10, 2020			
VIN Range 1:		NR	End: NR	☐ Not sequen	itial

Vehicle 6:	2019-2020 BM	W R1250RT			
	MOTORCYCLES				
Body Style :					
Power Train:					
Descriptive Information :	: Approximately 37 motorcycles were produced with a brake fluid reservoir cover which may not fully conform to FMVSS 122 Section 5.1.9(d).				
	Basis for recall population determination: Motorcycle production records were reviewed to determine the specific Model Year 2019-2020 BMW R 1250 RT motorcycles manufactured from $01/18/2019$ through $02/07/2020$ with an order option for a color-specific brake fluid reservoir cover.				
	Recall component difference to non-recall component: Recall motorcycles were produced with an optional brake fluid reservoir cover which may not fully conform to FMVSS 122 Section 5.1.9(d).				
Production Dates :	JAN 18. 2019 - I	FEB 07, 2020			
VIN Range 1:		NR	End: NR	Not sequential	
Vehicle 7:	2020-2020 BM	W R1250R			
Vehicle Type :	MOTORCYCLES	5			
Body Style :					
Power Train :					
Descriptive Information :	: Approximately 46 motorcycles were produced with a brake fluid reservoir cover which may not fully conform to FMVSS 122 Section 5.1.9(d).				
	Basis for recall population determination: Motorcycle production records were reviewed to determine the specific Model Year 2020 BMW R 1250 R motorcycles manufactured from $06/06/2019$ through $12/16/2019$ with an order option for a color-specific brake fluid reservoir cover.				
		an optional bra	o non-recall component: Reca ke fluid reservoir cover which		
Production Dates :	JUN 06, 2019 - I	DEC 16, 2019			
VIN Range 1:		NR	End: NR	☐ Not sequential	

Vehicle 8:	2020-2020 BMV	W R1250RS		
Vehicle Type :	MOTORCYCLES			
Body Style :				
Power Train:	GAS			
Descriptive Information :	: Approximately 17 motorcycles were produced with a brake fluid reservoir cover which may not fully conform to FMVSS 122 Section 5.1.9(d). Basis for recall population determination: Motorcycle production records were reviewed to determine the specific Model Year 2020 BMW R 1250 RS motorcycles manufactured from 06/05/2019 through 01/27/2020 with an order option for a color-specific brake fluid reservoir cover.			
	-	an optional bra	-	nt: Recall motorcycles were er which may not fully conform to
Production Dates :	IIIN 05 2019 - I	AN 27 2020		
VIN Range 1:		NR	End: NR	☐ Not sequential
Vehicle Type : Body Style : Power Train :	Approximately which may not a Basis for recall reviewed to det motorcycles ma option for a cold Recall componer	11 motorcycles fully conform to population dete ermine the spenufactured from the specific brakent difference to an optional brakent difference to the specific brakent difference to the speci	were produced with p FMVSS 122 Section 5 ermination: Motorcycleific Model Year 2019 m 02/19/2019 through fe fluid reservoir covers on on-recall componer	le production records were 0-2020 BMW R nine T Pure gh 02/06/2020 with an order
Production Dates :	FEB 18. 2019 - I	FEB 10, 2020		
VIN Range 1:	Begin:	NR	End: NR	☐ Not sequential

Description of Noncompliance:

Description of the This non-compliance recall involves the optional color-specific brake fluid

Noncompliance: reservoir cover. The cover may not fully conform to FMVSS 122 Section 5.1.9

(d).

FMVSS 1: 122 - Motorcycle brake systems

FMVSS 2: NR

Description of the Safety Risk: If the text on the brake fluid reservoir cover was confusing or misunderstood,

it could lead to an improper maintenance procedure.

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name 1: NR

Component Description: NR

Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name : GILLES TOOLINGGmbH

Address: 26, Op der Ahlkerrech

Grevenmacher FOREIGN STATES 6776

Country: Luxembourg

Chronology:

In mid-February, 2020, based upon an internal review of motorcycle accessory parts, BMW became aware that certain motorcycles produced for the US market (with an order option for a color-specific brake fluid reservoir cover) could have been released with a cover that may not fully conform to FMVSS 122 Section 5.1.9(d).

A review of regulatory requirements, and the language contained on the covers, confirmed that potentially affected motorcycles may not fully conform to FMVSS 122 Section 5.1.9(d). Motorcycle production records were reviewed to determine the number, and production date range, of potentially affected motorcycles.

BMW has not received any reports, nor is BMW otherwise aware, of any accidents or injuries related to this issue.

On March 12, 2020, BMW decided to conduct a voluntary non-compliance recall.

Description of Remedy:

Description of Remedy Program: The brake fluid reservoir cover will be replaced.

Owners will be notified by First Class mail and instructed to take their motorcycle to an authorized BMW motorcycle dealer to have the remedy performed for free. If this condition were to occur to a potentially affected motorcycle prior to this recall, the remedy would be covered by the BMW

Motorcycle New Vehicle Limited Warranty program. Therefore, reimbursement for a pre-notification remedy re Part 573.13 and Part

577.11 is not necessary.

How Remedy Component Differs Brake Fluid Reservoir Cover – p/n – (RnineT: 8404-098/-100/-102,

from Recalled Component: 1542056), (R1250: 8405-752/-753/-754, 9829547).

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: Notification to dealers occurred on April 24, 2020.

Notification to owners occurred on May 18, 2020.

When parts become available, anticipated mid-September, owner letters will be mailed prompting them to schedule their vehicle for the recall.

Planned Dealer Notification Date: MAR 27, 2020 - MAR 27, 2020 Planned Owner Notification Date: MAY 11, 2020 - MAY 11, 2020

* NR - Not Reported