

HUSQVARNA TECHNICAL BULLETIN HTB2011

MARCH XX, 2020

RECALL - STOP VEHICLE SALE NOTICE

FUEL SEEPAGE AT THE FUEL LEVEL SENSOR MOUNTING AREA AND FUEL PUMP MOUNTING AREA

AFFECTED MODELS:

2018, 2019, 2020 – 701 VITPILEN

2019, 2020 – 701 SVARTPILEN

RESTRICTIONS: AFFECTED MODELS ARE LINKED BY VIN IN HUSQVARNA DEALER.NET

INITIAL INFORMATION:

STOP VEHICLE SALE NOTICE: THE REMEDY FOR THIS RECALL IS NOT YET AVAILABLE. YOU WILL RECEIVE ANOTHER TECHNICAL BULLETIN ON THIS TOPIC AS SOON AS THE RECALL REPAIR IS AVAILABLE AND CAN BE COMPLETED ON AFFECTED MOTORCYCLES

Husqvarna Motorcycles North America, Inc. has decided that a defect which relates to motor vehicle safety exists with the motorcycle models and years listed above in which the fuel may seep or leak from the fuel level sensor and fuel pump mounting area. To ensure the highest level of safety, performance, reliability and customer satisfaction, Husqvarna Motorcycles is investigating the possibility of a fuel leak occurrence.

Dealers must immediately stop selling affected 701 SVARTPILEN AND VITPILEN motorcycles listed above. Vehicles will be locked out from retail registration in Dealer.net until the remedy is in place.

The remedy for this recall is not yet available. You will receive another technical bulletin on this topic as soon as the recall repair is available and can be completed on affected motorcycles.

In the interim, Husqvarna Motorcycles North America, Inc. has notified all registered owners of the above affected motorcycles by mail that if they experience an occurrence of fuel leakage we request that they stop riding their motorcycle and contact their local authorized Husqvarna Motorcycles dealer to have their motorcycle inspected. A copy of the customer letter is included in this bulletin.

If you are contacted by a customer that says their 701 SVARTPILEN AND VITPILEN listed above is seeping or leaking fuel at the fuel level sensor and fuel pump mounting area please contact the Husqvarna Motorcycles Dealer Services department by calling 855-282-1054.

Once the remedy is decided, registered owners will be informed again of the remedy to correct the defect in cooperation with their local Husqvarna Motorcycles dealer.

COPYRIGHT NOTICE

The user acknowledges that all components of this technical information are Husqvarna's and/or third parties' copyright protected property. Alteration, assignment, distribution and reproduction are forbidden.

LIMITATION OF LIABILITY

The information included in or available through this technical information may include inaccuracies or errors. In no event shall Husqvarna and/or its suppliers be liable for any damages whatsoever, arising out of or in connection with the use of this technical information. Please always refer to the Husqvarna owners and repair manuals for proper instructions or contact the Husqvarna Dealer Services Department. ©2020 Husqvarna Motorcycles North America, Inc. – All rights reserved