


ALA4 Stop Sale / Stop Delivery - Replacing fuel supply line



ALA4 Stop Delivery - Replacing fuel supply line

IMPORTANT REMINDER

IT IS A VIOLATION OF FEDERAL LAW FOR DEALERS TO DELIVER TO CUSTOMERS NEW VEHICLES IN THEIR

INVENTORY AFFECTED BY THIS NOTIFICATION UNTIL THESE VEHICLES ARE REMEDIED.

DEALERS SHOULD NOT SELL, LEASE, RENT, OR LOAN ANY NEW OR USED VEHICLES IN DEALER INVENTORY AFFECTED BY THIS NOTIFICATION PRIOR TO REMEDY. DEALERS GROUNDING LEASE RETURNS SHOULD REMEDY ALL AFFECTED GROUNDED VEHICLES.

Vehicle blocking

Vehicles must not be delivered to customers until the required remedial measure has been carried out. Therefore, please carry out following Stop Delivery, immediately.

Overview

On the affected vehicles, the quick connector of the fuel supply line may potentially loosen at very high temperatures in the engine compartment, which can lead to fuel leakage.

Model type	Cayenne Turbo (9YA) Cayenne Turbo S E-Hybrid (9YA) Cayenne Turbo Coupé (9YB)
Model year	2019-2020
Number of affected vehicles	337

Vehicle usage

The vehicles may only be driven for loading and unloading purposes in the transport chain. Further use is not permitted. Test drives are to be omitted.

Remedial measure

Will be communicated with availability of optimized parts (expected in late July 2020)

Should vehicles have already been delivered to customers in the meantime today, contrary to expectations, please report them to ryan.cooney@porsche.us

The further procedure for these vehicles will be communiacted at a later point of time.