



5 Stan Perkins Road Spartanburg, South Carolina 29307 USA 864-327-4744  
www.kymcousa.com

## **VOLUNTARY SAFETY RECALL**

July, 2020

NHTSA Recall# 20V350

### **Voluntary Safety Recall: KYMCO Like 150i, Potential ABS dysfunction**

Dear KYMCO Dealer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

#### **Defect Involved:**

**Kwang Yang Motor Co., Ltd. (KYMCO) has decided that a defect which relates to motor vehicle safety exists on all 2018 and select 2019 model year “Like 150i” vehicles. These vehicles have a magnetic ring in the speed sensor that may deteriorate prematurely causing ABS failure and the ABS light on the speedometer to illuminate. Without ABS, controlling the scooter in an emergency stopping scenario may be affected, increasing the risk of a crash.**

#### **Vehicles Involved and VIN Range:**

**All 2018 model year & select 2019 model year Like 150i units (1786 units total).**

#### **VIN Range of affected units:**

2018 VIN Range:

2019 VIN Range:

#### **Description of Defect:**

The defect is due to premature deterioration of a magnetic ring in the speed sensor caused by excessive lubricating grease.

#### **Plan of Action:**

KYMCO USA, Inc. will send the repair kits to all authorized KYMCO dealers based on the number of affected units purchased to ensure that each dealer has an adequate



5 Stan Perkins Road Spartanburg, South Carolina 29307 USA 864-327-4744  
www.kymcousa.com

quantity of kits on hand to perform the recall procedure in a timely manner. Additional repair kits are available upon request by the dealer.

KYMCO USA, Inc. will send letters to all registered owners (based off warranty registration with KYMCO USA, Inc.) of the affected units advising them of this voluntary recall and instructing them to make appointments for the repair of their vehicle at any authorized KYMCO dealer as soon as possible. Please schedule the repairs for the owners as soon as possible to prevent any risk as a result of this defect. We have included with this letter a list of customers who have been registered with KYMCO USA, Inc. sold by your dealership in our warranty system with affected Like 150i units. Please advise KYMCO USA, Inc. if there are any outstanding customers who have not been warranty registered so we can contact them immediately.

The repair kit (Part number: Like150-2020-Recall-Kit) contains the following items:

- Replacement magnetic ring
- Repair Instructions
- Warranty/Reimbursement Instructions

**Reimbursement for Recall:**

KYMCO USA, Inc. will provide the recall repair kits free of charge and pay pre-established KYMCO dealer labor rates for each repair performed. Kwang Yang Motor Co., Ltd. has assigned a flat rate code for this recall:

- Flat rate code: Like150-2020-Recall-Kit
- Flat rate time allocated: half an (0.5) hour

For any further questions, please contact KYMCO USA, Inc.

Phone: 888-716-0427

Email: [like1502020recall@kymcousa.com](mailto:like1502020recall@kymcousa.com)

We apologize for any inconvenience caused by this voluntary recall.

Kindest regards,

KYMCO USA, Inc.