

## **Parts Bulletin**

## TITI F

Recall R10029: Front Seat Belt Fastener, Model Year 2007 – 2018 S60CC, S60L, V60CC, S60, XC60, V60, XC70, V70, S80, S80L

CAT/NO:	CAR MARKET:	
R10029	United States and Canada	
ONS:	ISSUE DATE:	STATUS DATE:
	2020-09-21	2020-09-21
	Page 1 of 1	
	R10029	R10029 United States ONS: ISSUE DATE: 2020-09-21

"Right first time in Time"

Reference Bulletin: QB R10029

Volvo Car USA LLC and Volvo Car of Canada Ltd (Volvo) on behalf of Volvo Car Corporation, has decided to launch Recall R10029 on certain model year 2007 – 2018 60 Series, 70 Series and 80 Series vehicles.

Volvo has identified an issue regarding the front seat belt fastening, mounted on the outboard side of the front seat. The front seat belt fastening cable may, under certain circumstances, suffer from wear and fatigue if repeatedly bent over the seat cushion. This could cause damage to the cable, which could result in reduced or no seat belt restraint function.

The corrective action is to replace the front driver and passenger seat belt fastener.

A total of 307,928 U.S. and 24,057 Canadian vehicles are eligible for this recall.

The following part numbers apply:

Part Number	Description	Qty
32341045	End Fitting	2
32328849	Block	1