



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

July 31, 2020

Mr. Wayne Gates
Hyundai Motor America
10550 Talbert Ave
Fountain Valley, CA 92708

NEF-150JK
20V-447

Subject: Potential Loss of Steering Control

Dear Mr. Gates:

This letter serves to acknowledge Hyundai Motor America's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:
HYUNDAI/GENESIS G70/2020

Mfr's Report Date: July 31, 2020

NHTSA Campaign Number: 20V-447

Components:
STEERING

Potential Number of Units Affected: 2

Problem Description:

Hyundai Motor America (Hyundai) is recalling certain 2020 Genesis G70 vehicles. A component within the Rack Mounted Motor Driven Power Steering (R-MDPS) Assembly may have been manufactured incorrectly, possibly resulting in the steering locking or becoming difficult while driving.

Consequence:

A loss of steering control can increase the risk of a crash.

Remedy:

Hyundai dealers have replaced the R-MDPS Assemblies, free of charge, prior to the sale of the vehicles. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 004G.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please ensure the following requirements are met:

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components that need to be replaced to remedy this recall condition. This information should be provided in an amended 573 in the "Involved Components" section.

AMENDED 573 REQUIRED.

Please provide the Tier-2 Supplier information.

AMENDED 573 REQUIRED.

Please identify when the dealers were first notified of the safety defect in the affected vehicles.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, you are required to submit up to 6 recall quarterly reports. If however, both of the affected vehicles have been repaired, submit one recall completion rate report stating a 100% completion.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov. We look forward to working with you.

Sincerely,



Joshua Neff
Chief, Recall Management Division
Office of Defects Investigations
Enforcement