


IMPORTANT SAFETY RECALL 2020080015

This notice applies to your vehicle, VIN:
Update Software for Seat Belt Warning in the Instrument Cluster
NHTSA Recall #20V449

Mercedes-Benz USA, LLC

Christian Treiber Vice President Customer Services

September, 2020



- · A remedy is available for your vehicle.
- Schedule an appointment with your authorized Mercedes-Benz dealer as soon as possible.
- This repair will be provided free of charge.

Dear Mercedes-Benz Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has decided that a defect which relates to motor vehicle safety exists in certain Model Year ("MY") 2017-2019 C-Class, E-Class, E-Class Coupe/Convertible and CLS-Class vehicles. Our records indicate that your vehicle is included in the affected population of vehicles.

What is the CONCERN?

In certain MY 2017-2019 C-Class, E-Class, S-Class, E-Class Coupe/Convertible and CLS-Class vehicles, the seat belt warning system does not meet current production specifications. If the driver or front passenger seat belt is not fastened, the seat belt warning would not warn the driver as intended by means of a blinking warning lamp in the instrument cluster and by an audible warning tone, but only with a permanently activated warning lamp. Thus, the driver would not receive the full scope of intended warnings in the event of an unfastened seatbelt. An unfastened seatbelt increases the risk of injury in the event of a crash. The customer may be made aware of the issue by the absence of the blinking warning lamp and the audible warning tone if the vehicle s driven without the seat belt fastened.

What will your DEALER DO?

An authorized Mercedes-Benz dealer will update the software of the instrument cluster on the affected vehicles. <u>This service will be provided free of charge.</u> We are dedicated to always delivering the best customer experience, and respect for your time is a top priority. While the minimum repair time can be less than thirty minutes, your dealer can provide you with a better estimate of the overall time for this service visit. As a matter of normal service process, an authorized Mercedes-Benz dealer will also check for other repair measures which might be applicable to your vehicle which may increase the required working time.

What should YOU DO?



To find the most convenient authorized Mercedes-Benz dealer from your smartphone, scan the QR code to the left.

Information for Owners

For additional information and to schedule an appointment, please contact your preferred authorized Mercedes-Benz dealer at your earliest convenience. To locate authorized dealers see www.MBUSA.com/recall. Please mention you are scheduling an appointment to update the software for the seat belt warning in the Instrument Cluster under Recall Campaign # 2020080015. You may be asked for your 17-digit Vehicle Identification Number (VIN) which for your convenience is located above your name at the top of this letter.

<u>Impacts from COVID-19</u>: Your health and safety remain our top priority. The Mercedes-Benz dealerships remaining open for recall repairs and service are closely following the guidelines set forth by the CDC. **Free** Mobile Repair at your home or business as well as vehicle pick-up and delivery may be available. Your preferred authorized Mercedes-Benz dealer can confirm availability.

In the event that you are no longer the vehicle owner, or have had a change of address, please complete the reverse side and return the updated information in the enclosed envelope.

If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

A VIN-based recall lookup tool on our MBUSA.com website offers a search feature that will indicate whether a vehicle has been subject to a safety recall, and whether that vehicle has had the free remedy performed. See www.mbusa.com/recall. Should you have any questions or encounter any difficulty regarding this Recall Campaign, please contact an authorized Mercedes-Benz dealer. If for any reason a dealer is unable to remedy your situation, we are always happy to hear from you. Please contact us at 1-(800) FOR-MERCEDES (1-800-367-6372).

If an authorized Mercedes-Benz dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to https://www.safercar.gov.

We apologize for any inconvenience this situation may cause you.

Sincerely,

The Tube

Mercedes-Benz USA, LLC

IMP

If for any reason YOU NO LONGER OWN THIS VEHICLE OR have a CHANGE OF ADDRESS, please COMPLETE THE SECTION BELOW, place in the ENCLOSED ENVELOPE, and DROP IN ANY MAIL BOX. If possible, provide the name and address of the present owner

ORTANT	VIN:

so t	hat v	ve m	ay c	onta	ct th	iem.																							
	☐ LEASE, VEHICLE RETURNED														SOLD STOLEN OTHER														
	☐ NEW OWNER INFORMATION														☐ MY NEW NAME OR ADDRESS IS:														
																												T	
La	st Na	me, I	First	Nam	e	1			1	I	I	<u> </u>			<u> </u>	1	<u> </u>			1		1	I	1	1				
Street													•	•		•		•		•		•		Ар	t				
City													•		•		•		Sta	ate		ZIP							
Em	ail A	ddres	SS		1				1							1				1			ı	1					
Ph	one (ı	numl	bers (only)		I		1	1				<u> </u>	<u> </u>		Mob	ile (n	umbe	ers o	nly)	1	II.	1	1	1			<u>.I</u>	
Date						Sign	natu	re																					

**** PLEASE DO NOT DETACH. RETURN COMPLETE LETTER **** DO NOT USE THE ENCLOSED ENVELOPE FOR OTHER CORRESPONDENCE