



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

August 18, 2020

Ms. Larissa Stoffels
Exec Mgr, Vehicle Safety
Daimler Trucks North America LLC
4747 N. Channel Ave
Portland, OR 97217

NEF-150MR
20V-466

Subject: Engine Harness May Contact and Chafe

Dear Ms. Stoffels:

This letter serves to acknowledge Daimler Trucks North America LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

FREIGHTLINER/BUSINESS CLASS M2/2017-2021

Mfr's Report Date: August 7, 2020

NHTSA Campaign Number: 20V-466

Components:

ELECTRICAL SYSTEM:WIRING
ENGINE

Potential Number of Units Affected: 5,374

Problem Description:

Daimler Trucks North America, LLC (DTNA) is recalling certain 2017-2021 Freightliner Business Class M2 trucks. The engine harness may contact and chafe at various locations around the air compressor and the frame rail. If the wires are damaged, they may short circuit, possibly causing an engine stall.

Consequence:

A engine stall may increase the risk of a crash.

Remedy:

DTNA will notify owners, and dealers will inspect for adequate clearance between harness and engine, and for any engine harness damage. Vehicles with a damaged harness will receive a new harness. These repairs will be performed free of charge. The recall is expected to begin October 5, 2020. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-858.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please ensure the following requirements are met:

A description of how the products to be recalled differ from similar products that are not included in the recall (49 CFR 573.6 (c)(2)).

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:


You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,



Joshua Neff
Chief, Recall Management Division
Office of Defects Investigations
Enforcement