#### The information contained in this report was submitted pursuant to 49 CFR §573

# Part 573 Safety Recall Report

Manufacturer Name :Forest River, Inc.Submission Date :SEP 17, 2020NHTSA Recall No. :20V-562Manufacturer Recall No. :51-1228

### **Manufacturer Information :**

Manufacturer Name : Forest River, Inc. Address : 55470 CR 1 P.O. Box 3030 Elkhart IN 46515-3030 Company phone : 1-800-348-7440

## Vehicle Information :

Vehicle 1:	2018-2020 Co	achmen Sportso	oach Moto	orhom	nes	
Vehicle Type :	BUSES, MEDIU	JM & HEAVY VE	HICLES			
Body Style :	OTHER					
Power Train :	NR					
Descriptive Information :	stem extensio combination. I Sportscoach Sportscoach	n and stabilizer	configured   Forest Rive   2021 1   2020 6   2021 10   2020 1   2021 10   20201 14   2021 20   20201 14   20201 14   20201 20   20201 20   20202 20   20202 20   20202 20   20202 20   20202 20   20202 20   20202 20   20202 20   20202 20   20202 20   20202 20   20202 20   20 20   20 20   20 20   20 20   20 20   20 20   20 20   20 20   20 20   20 20   20 20	l with er Inc. ) 1		ve stem and wheel
	Sportscoach	S1A408DB-360		)18	10	
	Sportscoach	S1A409BG-360		)19	37	
	Sportscoach	S1A409BG-360			1	
Production Dates :	JUN 20, 2017	- AUG 13, 2020				
VIN Range 1:	Begin :	NR	End: I	NR		Not sequential



Number of potentially involved : 975 Estimated percentage with defect : 100 %

**Population :** 

# 20V-562

20V-562

Page 2

Vehicle 2:	2018-2021 For	rest River Inc. B	erkshir	e Motorhomes	
Vehicle Type :	BUSES, MEDIU	M & HEAVY VE	HICLES		
Body Style :	OTHER				
Power Train :					
Descriptive Information :	As per DTNA's	Recall 20V529	– Certai	n motorhome chassis equ	inned with a valve
Descriptive mornation.	-			red with a specific tire val	
				iver Inc. with all affected v	
	BEA34B-360	2021 6			
	Berkshire	BEA34QS-360	2018	34	
	Berkshire	BEA34QS-360	2019	44	
	Berkshire	BEA34QS-360	2020	25	
	Berkshire	BEA34QS-360	2021	4	
	Berkshire	BEA37A-380	2018	23	
	Berkshire		2019	19	
	Berkshire		2020	16	
	Berkshire	BEA37A-380	2021	5	
	Berkshire		2018	25	
	Berkshire		2019	10	
	Berkshire		2018	38	
	Berkshire	BEA39A-360	2019	39	
	Berkshire	BEA39A-360	2020	30	
	Berkshire	BEA39A-360	2021	9	
	Berkshire	BEA39B-360	2019	14 7	
	Berkshire	BEA40B-380	2018	7	
	Berkshire	BEA40BH-380		3	
	Berkshire Berkshire	BEA40C-380	2018	33	
	Berkshire	BEA40C-380 BEA40C-380	2019 2020	47 10	
	Berkshire	BEA40C-380 BEA40C-380	2020	8	
	Berkshire	BEA40C-380 BEA40D-380	2021	o 25	
	Berkshire	BEA40D-380 BEA40D-380	2019	13	
	Berkshire	BEA40D-380	2020	2	
	Berkshire	BEA40E-380	2021	25	
	Berkshire	BEA40E-380	2020	18	
	Berkshire	BEA43B-450	2018	6	
	Berkshire	BEA43B-450	2019	5	
	Berkshire	BEA43B-450	2020	1	
	Berkshire	BEA43C-450	2018	11	
	Berkshire	BEA43C-450	2019	15	
	Berkshire	BEA43C-450	2020	2	
	Berkshire	BEA45A-450	2018	27	
	Berkshire	BEA45A-450	2019	61	
	Berkshire	BEA45A-450	2020	4	
	Berkshire	BEA45B-450	2019	16	
	Berkshire	BEA45B-450	2020	3	
		ALIC 10, 0000			
Production Dates :				ND	
VIN Range 1:	Begin :	NR	End :	NR	Not sequential

20V-562

Vehicle 3:	2018-2020 Forest River In	c. Legacy		
Vehicle Type :	BUSES, MEDIUM & HEAVY	VEHICLES		
Body Style :	OTHER			
Power Train :	NR			
Descriptive Information :	As per DTNA's Recall 20V3 stem extension and stabili combination. DTNA suppli Recall 20V529 – Certain m and stabilizer configured w DTNA supplied Forest Rive Legacy LSA340BH-340 Legacy LSA340BH-340 Legacy LSA34A-340 201 Legacy LSA360RB-340201 Legacy LSA360RB-340201 Legacy LSA38C-340 201 Legacy LSA38C-340 201	zer configur ed Forest R otorhome c vith a specifier fr Inc. with 2018 2019 8 17 9 10 8 3 8 27	ed with a specific tire valviver Inc. with all affected v hassis equipped with a va fic tire valve stem and whe all affected vehicles. 2	e stem and wheel ehicles.As per DTNA' lve stem extension
<b>Production Dates :</b>	JUN 20, 2017 - AUG 13, 202	20		
VIN Range 1:1	Begin: NR	End :	ND	Not sequential

## **Description of Defect :**

	As per DTNA's recall 20V529, On affected chassis, the tire valve stem extension for the inner wheel may contact the outer wheel rim opening and become damaged. Extensive damage to the valve stem may result in a loss of tire pressure of the inner wheel
FMVSS 1 :	
FMVSS 2 :	NR
Description of the Safety Risk :	As per DTNA's recall 20V529, Motorhome vehicle drivers may not be required to hold a commercial driver's license and daily pre-trip inspections may not be required which would enable early detection of the issue. The potentially affected chassis population may not be equipped with a factory tire pressure monitoring system and visual inspection of the inner tire on a single drive axle motor home is difficult due to the close proximity of the motorhome body. Due to the high failure rate and reduced detectability, a loss of air pressure in the inner tire on a vehicle with a single drive axle may result in an overloaded outer tire. While DTNA has not received any reports of an incident related to this defect, extended driving with an overloaded tire may increase the risk of a crash.
Description of the Cause :	NR
	Operators may identify an audible rattling noise from the stem extension rubbing against the wheel opening while driving. Visual inspection during inspection or during maintenance may reveal stabilizer is dislocated, damage
The infor	mation contained in this report was submitted pursuant to 49 CFR §573

to the stem extension, or the rim, and low tire pressure of the inner tire.

**Involved Components :** 

Component Name 1: NR

Component Description : NR

Component Part Number: NR

## **Supplier Identification :**

### **Component Manufacturer**

Name : NR Address : NR NR

Country: NR

## Chronology :

On 9-9-2020 Forest River Inc. was notified of a pass through recall for DTNA 20V259. DTNA supplied all vehicles affected.

On 9-18-2020 Forest River's Corporate Recall Committee voted to recall.

DTNA will provide all reporting to NHTSA and Trans Canada

### **Description of Remedy :**

Description of Remedy Program :	This is the first letter in regard to this recall that you will receive. You will receive another notice when Daimler Trucks North America notifies its dealers and owners that a remedy without charge for this issue is available. If you have questions regarding this notice, please contact the Warranty Campaigns Department at (800) 547-0712, 7:00 a.m. to 4:00 p.m. Pacific Time, Monday through Friday, e-mail address DTNA.Warranty.Campaigns@Daimler.com.
	Difficient difficient difficient difficient

The information contained in this report was submitted pursuant to 49 CFR §573

How Remedy Component Differs from Recalled Component :	NR
Identify How/When Recall Condition was Corrected in Production :	NR
Recall Schedule :	
	Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.
	suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573