

Part 573 Safety Recall Report

20V-577

Manufacturer Name : Airstream, Inc.**Submission Date :** APR 16, 2021**NHTSA Recall No. :** 20V-577**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Airstream, Inc.

Address : 419 West Pike Street
PO Box 629 Jackson Center OH
45334-0629

Company phone : 937-596-6111

Population :

Number of potentially involved : 5

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2021-2021 Airstream Basecamp 16

Vehicle Type : TRAILERS

Body Style : UNKNOWN

Power Train : NR

Descriptive Information : The recall population was determined by completing an audit of vehicle records of the labels that were printed. The information on the labels match the tires on the trailers.

Production Dates : AUG 18, 2020 - SEP 21, 2020

VIN Range 1 : Begin : 1SMG4DC18MJ204900 End : 1SMG4DC19MJ205179 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : The tire information printed on the Federal Certification label and Tire Placard are incorrect. The information printed was for 255/55R18 - 50 PSI, when it should have been for ST225/75R15E - 80 PSI.

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : 567 - Certification

Description of the Safety Risk : Per the information contained on the labels, an owner could underinflate their tires installed on the trailer.

Description of the Cause : There was a product change regarding tires, and the information was not updated in the system in time to catch the first 5 units receiving the new tires.

Identification of Any Warning that can Occur : None

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

September 16, 2020 - Performed audit, discovered incorrect labels were being printed and placed on certain trailers. September 18, 2020 - 5 Basecamp units were identified as having incorrect labels. New labels were printed. Two of the five units were still on Airstream property, and were corrected. Three units had shipped to dealers, and one had retailed. September 21, 2020 - Labels were shipped to the dealers. 9/23/20-Decision was made to submit 573 for a non-compliance recall.

Description of Remedy :

Description of Remedy Program : Corrected labels will be sent to affected dealers for installation. This will be done at no cost to the owner.

How Remedy Component Differs from Recalled Component : The tire information has been corrected from 255/55R18 - 50 PSI to ST225/75R15E - 80 PSI.

Identify How/When Recall Condition was Corrected in Production : The issue was corrected on September 18, 2020.

Recall Schedule :

Description of Recall Schedule : Airstream sent the dealers and owner replacement labels on 9/21/20

Planned Dealer Notification Date : NOV 22, 2020 - NOV 22, 2020

Planned Owner Notification Date : NOV 22, 2020 - NOV 22, 2020

* NR - Not Reported